

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Cor Secs 26, 27, 34, & 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCS0 records Vol. 7 Page(s) 2987)

On side of mountain, set hemlock post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 26, 27, 34, & 35 marked T24S S26 on NE, R3W S35 on SE, S34 on SW and S 27 on NW face, 1 notch on S & 2 notches on E edges from which
A fir, 40" dia. bears N.40°E. 25 lks. mkd: T24S R3W S26 BT
A fir, 20" dia. bears S.35°E. 40 lks. mkd: T24S R3W S35 BT
A fir, 30" dia. bears S.74°W. 29 lks. mkd: T24S R3W S34 BT
A fir, 40" dia. bears N.33°W. 56 lks. mkd: T24S R3W S27 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - March 1968 - C.S. File 54/27-147

Reported as not fd.
Cat logged & burned, dense brush & reprod.

Burt Holt - For: Sun Studs Inc. - 12/1981 - M90-16

CONDITION REPORT ONLY
Found - 2" iron post protruding 6" above ground & a 2½" IP, 1 ft. West protrudes 8' (feet) above ground (no rec.) From the Corner:
48" fir stump bears N.40°E., 16.5 ft. (orig.)
48" fir stump bears N.30°W., (N.33°W.) 36.9 ft., w/W-nail in base.
38" windfall fir bears S.64°W., (S.74°W.) 19.2 ft.
SE BT is missing.

Steven P. Ness - For: Weyerhaeuser Co. - July 1993 - M117-35

Found - 1½" Iron Pipe.
56" D.Fir stump N.37°38'E., 18.5 ft. to center no 'W' nail.
Weyco. T tag on stump. (N.46°E., 15.8')
38" D.Fir snag 15' tall S.63°30'W., 31.4 ft. to center 29.87 ft. to 'W' nail. (S.66°W., 30.3 ft.)
57" D.Fir stump N.32°36'W., 39.5 ft. to center, 37.23 ft. to 'W' nail (N.27°W., 37.4 ft.)
Set - Cemented a 2½" Brass Cap to top of found 1½" Iron Pipe marked:
T24S R3W
S27 | S26
S34 | S35
1993 RLS 811
9" D.Fir, N.41°20'E., 29.3 ft. to center, could not measure to 'W' nail. Scribed "T24S R3W S26 BT"
continued next page

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Cor Secs 26, 27, 34, & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

15" D.Fir, S.30°27'E., 29.4 ft. to center, 28.54 ft. to 'W' nail. Scribed "T24S R3W S35 BT"
10" D.Fir S.34°52'W., 20.4 ft. to center, 19.89 ft. to 'W' nail. Scribed "T24S R3W S34 BT"
14" D.Fir N.26°42'W., 14.7 ft. to center, 14.14 ft. to 'W' nail. Scribed "T24S R3W S27 BT"

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 12/12/2024 - C.S. File 67/59-28

Found - 1½" iron pipe up 6", 2½"x10 ft. iron pipe loose on surface, FD brass cap loose on surface. (cap properly mkd)
Burnt-rotted, 49"x4 ft. D.Fir stump N.37°38'E., 18.0 ft. (rec. 18.5 ft) add 3½" mag nail right side center.
Burnt-rotted, 50"x7 ft. D.Fir stump N.32°36'W., 39.5 ft to center 37.23' to W nail.
15" D.Fir loose on ground burned scar, no position.
Burnt-broken-rotted 17"x7' D.Fir snag S.30°27'E., 29.4 ft., add 3½" mag nail right side center fully healed single blaze.
Sawn-burnt-rotted 12"x6½ ft. D.Fir stump S.34°52'W., 20.4 ft., fully healed single blaze, add 3½" mag nail right side center.
Burned-broken-very rotted 8"x8 ft. D.Fir snag N.26°42'W., 14.7 ft. blaze gone, add 3½" mag nail right side center.

Re-set - Brass cap using found BTs now proj 8" above ground. Reset found 2½"x10 ft. Iron Pipe 4.7 ft. north.

Note - Mon on small bench on gentle SW slope, burned old second growth to north and burned young trees south of cut line.
Mon is approx 220 ft. north of sharp switch back in gravel road.
Area burnt 9/2020
Compass decl. 14½°E.

OCRS COORDINATE SYSTEM
COTTAGE GROVE-CANYONVILLE ZONE
N 223280.035 E 244104.417