

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCS0 records Vol. 7 Page(s) 2991)

Set a cedar post 3x4" 3½ ft. long, 24" in the ground for ¼ sec. cor. marked ¼ sec. cor. mkd. ¼ S on W face from which
A hemlock, 8" dia., bears S.19°E., 32 lks., mkd: ¼ S BT.
A fir, 10" dia., bears N.21°W., 15 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - March 1968 - C.S. File 54/27-151

Condition report only
Found - Unrecorded 1/2" pipe & 1½"x8' marker pipe with "W" method BTs
30" Fir stump N.65°E., 20.8 ft., "W" nail & tag.
50" Fir stump S.72°W., 54.0 ft., "W" nail & tag.
We find no trace orig. BTs.

Dan Baker, For: Weyerhaeuser Co. - Dec. 8, 1983 - M90-48

Set - 2½"x36" iron pipe with brass cap with standard markings & "PLS 1978"
8" Fir N.57°E., 22.2 ft.
6" Hemlock, N.12°W., 26.6 ft.
Note- 1/2" monel pipe set by Weyer Co. bears N.80°15'49"E., 82.32 ft.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 10/1/2025 - C.S. File 67/61-33

Found - 2½" brass cap proj 5".
Burned off 16" x 6 ft. fir snag N.56°E.22.7 ft. (Rec N.57°E. 22.2 ft.) fully healed single blaze.
Broken, burnt 14" x 1 ft. Hemlock stub N.10°W. 26.6 ft. (Rec N.12°W.)
Monel pipe not found. Destroyed by landslide.
New - 6" D. Fir singed base S.6½°W. 24.0 ft. 3½" mag nail right side center.
23"x2 ft. burned, sawn D.Fir stump S.55°W. 35.8 ft. 3½" mag nail top center.
6" x 4 ft. broken snag N.54°W. 30.2 ft. 3½" mag nail right side center.
Notes - Mon. on N. edge. Large bench in recent clearcut. Older reprod to North.
Area burnt 9/2020
Compass decl. 14¼°E.
O CRS COORDINATE SYSTEM - COTTAGE GROVE-CANYONVILLE ZONE
43°28'03.23651 N. 123°01'51.27119 W. _____