

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCS0 records Vol. 7 Page(s) 2975)

Set cedar post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. marked ¼ sec. cor. mkd. ¼ S on N face from which
A fir, 24" dia., bears N.25°E., 33 lks., mkd: ¼ S BT.
A fir, 36" dia., bears S.60°E., 25 lks., mkd: ¼ S BT.

Weyerhaeuser Co., Donald Jordan Surveyor - Dec. 1965 - C.S. File 53/111-34

Found - 24" Fir, now 28", face not cut out but face line visible on top of stump.
36" Fir S.60°E., 16.5 ft., now fir stub, 10' high, face not grown, scribing visible. (This information placed on the orig. BTs by the 1944 Weyerhaeuser Co. survey didn't agree with the orig. 1883 survey. I accepted the orig. BTs disregarded the 1944 data & set the corner on the basis of the orig. "call" distances)
Set - 1"x30" alum. pipe, from which
Orig. 28" Fir stump N.32°E., 21.8 ft. "W" nail & plate.
Orig. 36" Fir stub S.64°E. 16.5 ft. "W" nail & plate
Logged 1963.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - March 1968 - C.S. File 54/27-151

Reported as not found
Apparently destroyed by new log road & landing.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 10/4/2025 - C.S. File 67/61-32

Not found. Searched for with GPS tie. No evidence found.