

PRIMARY CORNER DESCRIPTION SW Cor Samuel Driver DLC 41

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>DLC Survey by - Dennis Hathorn, under contract dated Sept 1856 (DCSO DLC records Pg 150)</p> <p>-----</p> <p>Set post - from which</p> <ul style="list-style-type: none">An Oak, 10" dia., bears S.30°E., 98 lks.An Oak, 18" dia., bears N.48°W., 91 lks.
<p>Gene Richardson & Edwin Woodford - 1945 - No record source found.</p> <p>-----</p> <p>Set - A 2" x 36" I.P. Set from old BT: 18" Oak, N.48°W., 91.0 lks.</p> <p>Marked the following new bearing trees:</p> <ul style="list-style-type: none">15" W.Oak, N.4°05'E., 164.3'.7" W.Oak, S.40°20'W., 102.4'.
<p>Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Jan. 21, 2014 - C.S. File 67/41-14</p> <p>-----</p> <p>Found - A 2"x36" IP now a 2" I.D. iron pipe, leaning approx. 0.6 westerly from plumb and protruding 10" above ground. 1945</p> <p>(Measured from plumb position of fd. mon.)</p> <ul style="list-style-type: none">An Oak 10" dia., now a possible shallow root depression; bears S.30°E., 64.7 ft. (as per record) OBTAn Oak 18" dia., now a 27" dia., W.Oak with a previously opened blaze (now rotted away with no face or scribing remaining) This tree bears N.48°W., 58.6 ft. (rec. N.48°W., 60.1 ft. would be a reasonable slope measurement) OBT.A 15" W.Oak now a 23" dia., W.Oak with a fully healed double blaze; bears N.4°E., 163.2 ft. (rec. N.4°05'E., 164.3 agrees well to center of trunk at breast height) 1945A 7" W.Oak now a 12" dia., W.Oak with blazing no longer visible; bears S.4¼°W., 102.4 ft. (as per rec) 1945 <p>New - Fd. 2" iron pipe is returned to plumb position; and now protrudes 8" above ground.</p> <ul style="list-style-type: none">A 13" dia., W.Oak scribed "SW DLC 41 CS" "BT" on a double blaze; bears S.76½°E., 32.7 ft. <p>Note - Monument is near top of broad NE running ridge on a moderate NW slope in an open oak woodland. Compass decl. 15½°E.</p>
<p style="text-align: right;">1</p>