

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 041060

PRIMARY CORNER DESCRIPTION E SE Cor Samuel Driver DLC #41

Alias	Description
Alias	Description
Alias	Description
Alias	Description

DLC Survey by - Dennis Hathorn, under contract dated Sept 1856 (DCSO DLC records Pg 151)

Set post for cor. - from which
A Fir, 24" dia., bears S.79°E., 188 lks.
A Fir, 24" dia., bears N.71°E., 252 lks.

Douglas Co. Surveyors Office - C.E. Roberts, Co. Surveyor - Aug. 1904 - FB 9 Pg 1

Fir, 18" dia., bears S.75°E., 12 lks.
Fir, 12" dia., bears S.77°W., 24 lks.

Douglas Co. Surveyors Office -Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone -April 1963 - C.S. File 53/9-58

Found - Splintered Fir stump, now 60", S.79°E., 124.1'. (Slope dist.) fd. good reverse scribing "BT"
50" Fir stump, N.71°E., 166.3', (slope dist.) Cut open & fd. scribing.
2 Fir stumps near corner, both with scribing "BT" which I assume were marked by Roberts in 1904. However, neither of them fits of them fits corner as set. No combination or juggling of bearings & distances would make it possible to set a corner from these stumps.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1963
T24S R4W E SE DLC 41
16" D.Fir, N.43½°E., 123.4', mkd: E SE DLC 41 CS BT
14" D.Fir, N.77°E., 82.7' (88' on 20° slope) mkd: ESE DLC 41 CS BT
Note - Corner lies on very steep NW slope.