

PRIMARY CORNER DESCRIPTION SW Cor Jacob Pitman DLC #43

Alias	Description

<p>DLC Survey by - Dennis Hathorn, under contract dated Sept 1856 (DCSO DLC records Pg 153)</p> <p>-----</p> <p>Set post for cor. - from which An Oak, 24" dia., bears N.48°E., 816 lks.</p>	
<p>Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - May 1963 - C.S. File 53/9-70</p> <p>-----</p> <p>Found - Old Oak, down several years, N.48°E., 538.6', cut open &amp; fd. good scribing.</p> <p>Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1963 T24S R4W SW DLC 43   8" W.Oak, S.69°E., 55.6', mkd: SW DLC 43 CS BT. 26" D.Fir, S.26°W., 77.7', mkd: SW DLC 43 CS BT.</p> <p>Corner lies on open NE slope, near top of ridge.</p>	
<p>Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Dec. 17, 2013 - C.S. File 67/41-10</p> <p>-----</p> <p>Found - A 2½" dia., brass cap (properly mkd) on a 1" I.D. iron pipe protruding 10" above ground and leaning southerly 0.6+ ft.</p> <p>Accessories are measured from plumb position of BC monument.</p> <p>No evidence remains of the Orig. BT.</p> <p>Two 1963 BTs are in good condition.</p> <p>An 8" W.Oak now 17" dia., W.Oak with a fully healed double blaze; bears S.69°E., 55.6 ft (as per rec)</p> <p>A 26" D.Fir now a 50" dia., D.Fir with a fully healed double blaze; bears S.26°W., 77.7 ft. (as per rec)</p> <p>New - A 6" and 10" dia., fir root that caused BC monument to tilt southerly are axed and chain sawn away and monument is returned to its plumb position. Monument now protrudes 11" above ground.</p> <p>A 16" dia., D.Fir scribed "SW DLC 43 CS" "BT" on a double blaze; bears N.22°E., 15.2 ft.</p> <p>A 10" dia., D.Fir scribed "SW DLC 45 CS" "BT" on a double blaze; bears N.36½°W., 16.0 ft.</p> <p>Note - BC monument is on moderate NE slope in older reprod fir forest with an oak and hawthorn under story. Compass decl. 15½°E.</p>	
<p>1</p>	