

PRIMARY CORNER DESCRIPTION SSW Cor Wm Howard DLC #44

Alias 045060 Description ESE Cor Elizabeth Johnson DLC#45
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

DLC Survey by - Dennis Hathorn, under contract dated Sept 1856 (DCSO DLC records Pg 155)

Set post SW cor. claim 44 and NE cor. claim 45 - from which:
A Fir, 50" dia., bears N.24°W., 371 lks.
An Oak, 12" dia., bears S.12°W., 58 lks.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy -
Vernon Tracy - Mike Stone - May 1963 - C.S. File 53/9-77

Found - 66" dead Fir snag N.24°W., 244.9', opened & found
good scribing.
No trace of SW tree.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1963
T24S R4W E SE | S SW
DLC 45 | DLC 44
New BTs- 10" D.Fir, N.43°E., 3.3', mkd: S SW DLC 44 CS BT.
8" D.Fir, N.67°W., 8.5', mkd: E SE DLC 45
Corner lies on NW slope in dense thicket of young Fir timber.

Fd. OK by Harvey Christensen, 9/2001 - M 138-80

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch
- 12/11/2013 - C.S. File 67/41-6

Found - 2½" dia., brass cap (properly mkd) on a 1½" I.D.
iron pipe firmly set and protruding 8" about
ground.
A fir, 50" dia., now a fallen and rotted 50"+ dia.,
D.Fir with a previously opened blaze showing the
orig. scribing "BT" The broken 3 ft. tall stump
of this tree bears N.24°W., 244.9 ft. (As per
rec) OBT
No evidence of orig. SW BT is found.
A 10" D.Fir now a 19" dia., D.Fir with a fully
healed double blaze; bears N.43°E., 3.3 ft. (as
per rec.) 1963
An 8" D. fir now an 11" dia., D.Fir with a fully
healed double blaze; bears N.67°W., 8.5 ft. (as
per rec) 1963
New - A 15" dia., D.Fir scribed "SSW DLC 44 CS" "BT" on a
double blaze; bears S.46°E., 11.6 ft.
A 7" dia., D.Fir scribed "X" "CSBT" on a high-low
blaze; bears S.67½°W., 26.8 ft.
Note - BC monument is on moderate NW slope near North edge
of thinned older reprod fir forest.
Compass decl. 15½°E.