

PRIMARY CORNER DESCRIPTION ESE Cor. J.H. Smith DLC #46

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>DLC Survey by - Dennis Hathorn, under contract dated Sept 1856 (DCSO DLC records Pg 157)</p> <p>-----</p> <p>Set post for cor. - from which</p> <p> An Oak 15" dia., bears N.25°E., 53 lks.</p> <p> An Oak, 18" dia., bears N.35°E., 74 lks.</p> <p> An Oak, 6" dia., bears N.35°W., 43 lks.</p>
<p>BLM Resurvey by C. Albert White & Norman J. McDonald, Cadastral Surveyors, under Group #'s 243, 350, & 513, surveyed April/July 1963 - (DCSO records Vol. 32 Page(s) 13471)</p> <p>-----</p> <p>Fd. corner, mkd by a corner of fences extending N & W.</p>
<p>Donald Bentz - For: Knight Ranch - Surveyed Nov. 1980, Map filed Jan. 1982 - M 91-2</p> <p>-----</p> <p>Set - 5/8" iron rod 2' west of fence line from which:</p> <p> An 18" snag in fence corner bears South 9.0', fence runs North & West.</p> <p>Corner is 30' East of ridge top and 18' East of North-South skid road.</p>
<p>BLM dependent resurvey by James E. Jelly, Cadastral Surveyor, under Group #979, surveyed May/Sept. 1979 (DCSO records Vol. 42 Page(s) 16385)</p> <p>-----</p> <p>The exterior cor. on the E. bdy of DLC #46, reestablished at proportionate distance and recorded by Bentz in 1979, and is accepted as the best available evidence of the position of the orig. cor., monumented with an iron rod, 5/8" dia., firmly set, projecting 6" above ground.</p> <p>At the corner point</p> <p>Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:</p> <p> T24S R4W</p> <p> <u>DLC 46 S 15</u></p> <p> S 22</p> <p> 1979</p> <p>from which</p> <p> An iron post, 28" long, 2½" dia., set 24" in the ground, for a reference monument, bears N.85½°E., 62 lks., with brass cap mkd: T24S R4W S15 RM 1979 and an arrow pointing to the corner.</p> <p> An Oak, 5" dia., bears N.69¼°W., 42 lks., mkd: C 46 BT.</p>
<p>continued next page</p>

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 046060

PRIMARY CORNER DESCRIPTION ESE Cor. J.H. Smith DLC #46

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Stephen J Flause - Mike Koch -
3/5/2015 - C.S. File 67/42-16

Found - Bentz $\frac{5}{8}$ " I.R. not seen (may be buried on edge of BC
monument below)
1979 BLM $3\frac{1}{4}$ " dia., Brass cap (properly mkd) on a $2\frac{1}{2}$ "
I.D. iron pipe firmly set protruding 6" above
ground.
1982 Bentz noted 18" snag gone.
 $3\frac{1}{4}$ " dia., brass cap with the stamping "T24S R4W S15"
firmly set protruding 4" above RM
ground; bears N.83°E., 40.7 ft. ←
(rec. N.85½°E., 40.9 ft) 1979 1979
5" Oak BT is gone (removed by land clearing)
The BC monument for S15|S14 bears East 299.0 ft. (Bentz rec
N.89¼°E. 299.2') S22|S23
New - A 10" dia., I.Cedar scribed "ESE DLC46 CS" "BT" on
a double blaze; bears S.60½°W., 54.6 ft.
A 5" dia., D.Fir scribed "X" "CSBT" on a high-low
blaze; bears N.27°W., 4.2 ft.
Note - Corner monument is approx. 30 ft. easterly from top
of NE-SW running high ridge. Monument is n
scattered Fir, Cedar, Oak, and Madrone reprod.
Compass decl. 15¼°E.