

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; and S. 31, T23-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 6 Page(s) 2272)

Set ¼ sec. post, from which
A Y.Oak 8" dia., bears N.5°E., 65 lks. dist.
A W.Oak 10" dia., bears S.40°E., 84 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; Mike Stone, crew - Feb 1963 - C.S. File 53/9-124

Found - Rotten Oak log, S.40°E., 55.4 ft., picked rotten wood apart and found good reverse scribing "¼S". Small depression in ground, possible stump hole, N.5°E., 42.9 ft.

Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 4 W
¼ S 31
S 6
T 24 S R 4 W
1963

New BTs- 11" D.Fir N.29°W., 17.6 ft. mkd. ¼ S31 CS BT.
(?) D.Fir S.11°W., 22.4 ft. mkd. ¼ S6 CS BT.
Corner lies 8 ft. South of E. and W. fence line, near NW. corner of patch of 2nd growth Fir timber.

Fd. OK, May 1981 by R. Quimby - M 79-77

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Oct. 22, 2013 - C.S. File 67/40-19

Found - A 2½" dia., brass cap (properly mkd) on a 1" I.D. iron pipe is firmly set and protrudes 14" above ground. 1963

Possible evidence of one OBT noted as fd. rotten log with scribing in 1963, now a distinct root-hole bearing S.40°E., 55.4 ft. (as per record). This root-hole now has a 12" dia., oak growing from it but all of previously fd. OBT evidence is gone.
An 11" D.Fir now a 14" dia., 1/2" tall very rotted D.Fir stump with no blaze or scribing evidence remaining; bears N.31°W., 17.6 ft. (rec. N.29°W., 17.6 ft.) 1963

A (?) D.Fir now a 29" dia., D.Fir with a fully healed double blaze; bears S.11°W., 22.4 ft. (as per record) 1963

continued next page

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 140700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; and S. 31, T23-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

New - A 9" dia., I.Cedar scribed "¼ S31 CS" "BT" on a double blaze; bears N.66¼°E., 31.9 ft.
A 9" dia., W.Oak scribed "¼ S6 CS" "BT" on a double blaze; bears S.58½°E., 15.9 ft.
A 12" dia., B.Oak scribed "¼ S31 CS" "BT" on a double blaze; bears N.42¼°W., 23.0 ft.
Note - BC monument is 8 ft. south of an E-W fence line and approx. 350 ft. west of Elkhead Rd. (Co. Rd. #50)
Monument is on gentle north slope in mixed medium aged fir, oak, maple, madrone and some cedar.
Compass decl. 15½°E.