

PRIMARY CORNER DESCRIPTION Cor. Secs 29, 30, 31, & 32

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Gordon & Gardner, Contract #52 dated Feb. 1855 (DCSO records Vol. 7 Page(s) 3047-48)

Set post for sec. from which

- A B.Oak, 20" dia., bears S.82°E., 25 lks.
- A B.Oak, 10" dia., bears N.51°E., 14 lks.
- A B.Oak, 18" dia., bears S.64°W., 30 lks.
- A B.Oak, 20" dia., bears N.57°W., 30 lks.

Douglas Co. Surveyors Office - F.C. Frear, Dep. Co. Surveyor - Witness: Alva Manning and Harrison Manning - Feb. 1917 - FB 43 Pg 54

Renew from old BT

Set in a 8"x10"x24" sandstone from which

- A 14" Fir, bears S.65½°E., 10½ lks.
- A 12" Fir, bears S.27¼°W., 24 lks.

Douglas Co. Surveyors Office -Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - May 1963 - C.S. File 53/9-83

Found - Rock set by Frear, "X" cut in top, rock firmly set. Rotten remnant of Fir stump S.65½°E., 7.0', not enough left to find any marks.

No trace of Frear's other BT or any of the Originals.

Corner is nearly in the center of power line R/W. Location fits call on ridge top in Orig. gov't notes.

DID NOT SET BRASS CAP

New BTs- 8" Madrone, S.81°E., 105.4', mkd: T24S R4W S32 CS BT
8" D.Fir, N.59°E., 160.0', mkd: T24S R4W S29 CS BT
9" D.Fir, N.73°W., 82.6', mkd: T24S R4W S30 CS BT
10" D.Fir, S.72°W., 98.2', mkd: T24S R4W S31 CS BT

Note - Corner is in E & W fence line, 7' West of fence corner, fences East, West & North.

BLM dependent resurvey by James E. Jelly, Cadastral Surveyor, under Group #979, surveyed May/Sept. 1979 (DCSO records Vol. 42 Page(s) 16404-05)

The sec. cor. is perpetuated and recorded by Frear in 1917, from orig. evidence no longer in existence & further perpetuated and recorded by Godfrey in 1963, monumented with a sandstone, 24x10x8" firmly set, projecting 4" above ground, mkd. X on top, from which the remains of a BT mkd. by Frear: (Cont. next page)

PRIMARY CORNER DESCRIPTION Cor Secs 29, 30, 31, & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A root hole, bears S.65°E., 10½ lks., with a down Fir alongside, 8' dia., with decayed blaze, no marks visible.

and the remains of BTs mkd. by Godfrey

A Fir, 12" dia., bears N.59°E., 242 lks. w/healed blaze.

A Madrone, 10" dia. bears S.81°E. 159 lks. w/healed blaze.

A sawed Fir stump, 17" dia., bears S.72°W., 149 lks. w/healed blaze

A sawed Fir stump, 15" dia., bears N.73°W., 125 lks., w/healed blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

T 24	S	R 4	W
	S 30	S 29	
	S 31	S 32	
	1979		

No other suitable trees available within limits.

Douglas County Surveyors Office - Randall Smith & Stephen Flause - 4/17/95 - C.S. 64/63-7

Found - None, evidence of road work & fence building in area

9" now 15" dia, 2' high rotted D.Fir stump, with scribing found "BT", bears N.73°W., 82.6'

8" now 13" dia, Madrone, with a fully healed single blaze, bears S.83°E., 105.4'

8" now 16" 3' high D.Fir stump, with a fully healed single blaze, bears N.59°E. 160'

Set - 2 3/8" Dia. DCSO Brass cap on a 1 3/8" O.D. by 32" long iron pipe is set at a position determined from BT's, protrudes 7" above ground.

NE corner of power line tower, where it meet 3' dia 2' high concrete post at NE cor., bears S.11½°E., 305.2'. (No. "4 PP&L - BPA 42").

5/8" I.R. with alum. cap stamp, "B0-1 1995", bears N.8 3/4°W., 46.7', protrudes 4" above ground.

No reasonable trees in vicinity

Corner is 2' south of a east-west fence and 11' west of dirt road centerline, corner lies near top of ridge in power line easement.

Fd. Ok by H. Christensen, 1/23/1996 - M 123-36