

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855
(DCSO records Vol. 7 Page(s) 3049)

Set 1/4 sec. post from which
 A Fir, 18" dia., bears N.31°W., 55 lks.
 A B.Oak, 24" dia., bears S.71°E., 40 lks.

Douglas Co. Surveyors Office -H.L. Eppstein, Co. Surveyor -
Witness: W. Frear - 1/9/1928 - "Old" Cor. Book Pg. 43

Set post for corner from an old Fir BT, other tree gone, mkd
new trees as follows:
 Fir, 36" dia., N.73°E., 115 lks.
 Fir, 15" dia., N.74°W., 107 lks.

Douglas Co. Surveyors Office - James Byron - Milo Godfrey &
Clete Putman - May 1960 - C.S. File 49/124-55

Found - Both BTs as recorded by Frear (Eppstein?). Both BTs
now stumps, partly rotted. Both show good scribe mks
Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE, 1960
 1/4 S30/S29 T24S R4W
 6" B.Oak, bears N.66°W., 20.1', scribed 1/4 S30 CS BT.
 8" R.Fir, bears S.72°E., 62.5', scribed 1/4 S29 CS BT.

Douglas Co. Surveyors Office -Milo E. Godfrey, Deputy Co.
Surveyor - Vernon Tracy - Mike Stone - May 1963 - C.S. File
53/9-82

Found - Both BTs mkd. in 1960, but brass cap gone; falls in
cat road.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE, 1963
 1/4 S30/S29 T24S R4W
Trees mkd. in 1960 as follows
 7" B.Oak, N.66°W., 20.1', scribing still visible "1/4
 S30 CS BT"
 9" D.Fir, S.72°E., 62.5', scribing still visible "1/4
 S29 CS BT"
New BT - 9" D.Fir, N.12°W., 44.7' mkd: 1/4 S30 CS BT.
Note - Corner lies just west of power line, Fir BT in sec.
29 in power line R/W will probably have to be cut
before limbs reach wires.

(Cont. next page)

1

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by James E. Jelly, Cadastral Surveyor, under Group #979, surveyed May/Sept. 1979 (DCSO records Vol. 42 Page(s) 16405-06)

The ¼ cor. of secs. 29 & 30, perpetuated and recorded by Frear in 1931 (Eppstein, 1928?) from orig. evidence no longer in existence, and further perpetuated and recorded by Godfrey in 1960-63, monumented with an iron post, 1¼" dia., firmly set, projecting 1" above ground, with a properly mkd. brass cap.

from which the remains of BTs mkd. by Godfrey

A sawed Fir stump, 10" dia., bears S.72°E., 95 lks., with healed blaze.

A B.Oak, 10" dia., bears N.66°W., 31½ lks. with healed blaze.

A sawed Fir stump, 10" dia., bears N.12°W., 67½ lks., with healed blaze.

and a new reference monument

An iron post, 28" long, 2½" dia., set 24" in the ground, for a reference monument bears S.73°E., 9½ lks., with brass cap mkd: ¼ S29 RM 1979 and an arrow pointing to the corner.

Fd. BC 11/1992 by Mark Heimbürger M116-18

Fd. ok by H. Christensen - 1/23/1996 - M 123-36