

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 5 & 8

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Gordon & Gardner, Contract #52 dated Feb. 1855 (DCSO records Vol. 7 Page(s) 3054)

-----

Set 1/4 sec. post from which  
A Fir, 8" dia., bears N.20°E., 112 lks.  
A Laurel, 3" dia., bears S.25°E., 150 lks.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - Feb/March 1963 - C.S. File 53/9-22

-----

Found - 42" Fir, N.20°E., 73.9', recently uprooted, chopped open & fd. scribe.  
No trace of SE BT

Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1963  
T24S R4W 1/4 S5/S8  
8" W.Fir, S.31°W., 119.2', mkd: 1/4 S8 CS BT.  
11" I.Cedar, N.44°E., 67.5', mkd: 1/4 S5 CS BT.  
A fence corner, fences E, W, and North bears N.75°W., 21 ft.

Fd. & used in BLM dependent resurvey by James E. Jelly, Cadastral Surveyor, under Group #979, surveyed May/Sept. 1979 (DCSO records Vol. 42 Page(s) 16408)

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under special instructions and Group No. 2210, surveyed Oct./Nov. 2008 - (DCSO records Vol. 57 Page(s) 22357-8)

-----

The 1/4 sec. cor. of secs. 5 and 8, monumented with an iron post, 1 1/4" dia., firmly set, projecting 5" above the ground, with brass cap (properly) mkd.  
from which the remains of an original bearing tree  
A roothole bears N.20°E., 73.9 ft., alongside of which is a displaced fir stump, 36" dia., with no marks visible. and the remains of BTs mkd. by Godfrey, in 1963, reported by Jelley in 1979  
A cedar, 31" dia., bears N.44°E., 67.1 ft., with a healed blaze. (Record, 68.6 ft.)  
A sawed fir stump, 32" dia., bears S.29 3/4°W., 119.5 ft., with no marks visible. (Record, S.31°W.)  
and a new bearing tree  
A fir, 4" dia., bears S.29 1/4°E., 17.1 ft., mkd. X BT.  
Each new bearing tree has a 2 1/2" x 1/4" magnetic nail (Mag Nail) driven at the base right side-center.