

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Cor. Secs 8, 9, 16, & 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855
(DCSO records Vol. 7 Page(s) 3046)

Set a post of secs. 8, 9, 16, & 17 from which
A B.Oak, 20" dia., bears N.40°W., 45 lks.
A B.Oak, 15" dia., bears N.46°E., 41 lks.
A B.Oak, 18" dia., bears S.59°W., 28 lks.
A B.Oak, 20" dia., bears S.10°E., 141 lks.

Douglas Co. Surveyors Office -Milo E. Godfrey, Deputy Co.
Surveyor - Vernon Tracy - Mike Stone - Feb/March 1963 - C.S.
File 53/9-34

Found - Oak, S.10°E., 93.1', down & badly rotted, stump hole
plain. Fd. good reverse scribing "S16 T24S R4W
BT"

Rotten Oak stump N.40°W., 29.7'. Trunk of tree
pushed out of position, good reverse scribing
visible on trunk of tree.

Upper portion of rotted Oak tree S.59°W., 18.5', no
stump hole found. Could not find where tree had
stood. No marks found.

No trace of NE BT.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE, 1963

T24S R4W

S8 | S9

S17 | S16

36" I.Cedar N.30°W., 14.0', mkd: T24S R4W S8 CS BT.

9" D.Fir, S.51°W., 20.6', mkd: T24S R4W S17 CS BT.

7" D.Fir, S.8°E., 16.9', mkd: T24S R4W S16 CS BT.

7" W.Fir, N.45°E., 24.3', mkd: T24S R4W S9 CS BT.

Note - A N & S fence line bears East 8' from corner.

Fd. & used in BLM dependent resurvey by James E. Jelly,
Cadastral Surveyor, under Group #979, surveyed May/Sept. 1979
(DCSO records Vol. 42 Page(s) 16398-99)