

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 5

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Oscar F. Thiel, Contract #658, May 1896 (DCSO records Vol. 7 Page(s) 3073)

-----

Set a sandstone 15x12x7 ins., 10 ins. in the ground for ¼ sec. cor. mkd: ¼ on West face, from which

- A Fir, 9" dia., bears S.86°W., 4 lks., mkd: ¼ S BT.
- A Fir, 20" dia., bears N.62°E., 14 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office -Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - Feb./March 1963 - C.S. File 53/9-26

-----

Found - Rock as called for in Gov't. notes faint marks visible on West face.

- 10" Fir snag, S.86°W., 2.6', previously opened, scribing visible.
- 29" D.Fir, N.62°E., 9.2', shows very plain axe scar. Did not open.

Along side east side of rock

Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1963  
T24S R4W ¼ S5/S4

24" D.Fir, S.44°W., 15.8', mkd: ¼ S5 BT.

Top of ridge running nearly North & South bears West approx. 250 feet.

BLM dependent resurvey by James E. Jelly, Cadastral Surveyor, under Group #979, surveyed May/Sept. 1979 (DCSO records Vol. 42 Page(s) 16401-02)

-----

From the ¼ sec. cor. of secs. 4 & 5, perpetuated and recorded by Godfrey in 1963, monumented with an iron post, 1¼" dia., firmly set, projecting 8" above ground, with properly marked brass cap.

From which the remains of the orig. BTs

- A sawed Fir stump, 25" dia., bears N.62°E., 14 lks., with healed blaze.
- A sawed Fir stump, 13" dia., bears S.86°W., 6 lks., with fragmentary scribe marks visible on open blaze. (Rec. 4 lks.)

and the remains of a BT mkd. by Godfrey

- A root hole, bears S.31°W., 28 lks., with a down fir alongside, 22" dia., no marks visible.

and a new BT

- A sawed Fir stump, 15" dia., bears S.64½°W., 9½ lks., mkd: ¼ S5 BT.

No other suitable accessories available within limits.

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 5

Alias	Description

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under special instructions and Group No. 2210, surveyed Oct./Nov. 2008 - (DCSO records Vol. 57 Page(s) 22356)

-----  
The ¼ sec. cor. of secs. 4 & 5, monumented with an iron post, 1¼" dia., firmly set, projecting 12" above the ground, with brass cap (properly) mkd.

from which the remains of an original bearing tree

A sawed fir stump, 26" dia., bears N.62°E., 9.2 ft., with a healed blaze.

and the remains of a BT mkd. by Godfrey, in 1963, reported by Jelley in 1979

A roothole bears S.31°W., 18.5 ft., alongside of which is the fir trunk, 20" dia., with no marks visible.

and the remains of a bearing tree mkd. by Jelley in 1979

A sawed fir stump, 15" dia., bears S.64½°W., 6.3 ft., with scribe marks X S5 BT visible on an open blaze.

and new bearing trees

A fir, 12" dia., bears N.30¼°E., 7.3 ft., mkd. ¼ S4 BT.

A fir, 12" dia., bears S.73°W., 9.0 ft., mkd. ¼ S5 BT.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise noted.