

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 340100

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 33; & 4 T25-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855
(DCSO records, Volume 7 Page 3027)

Set ¼ sec. post, from which
A Fir 30" dia. bears N.40°W., 91 lks. dist.
A Laurel, 3" dia. bears S.63°W., 14 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy -
Vernon Tracy; Clete Putnam, crew - May 1963 - C.S. 53/9-16

Looked for, not found. Fd. 3-way fence cor. and yellow tag.
No BTs.

Bureau of Land Management Dependent Resurvey - James Jelley
Group #979 Surveyed May-Sept. 1979 (DCSO records, Volume 42
Page 16377-78)

Point for the ¼ sec. cor. of secs. 4 and 33, at proportionate
distance; there is no remaining evidence of the original cor.
Set an iron post, 28" long 2½" dia. 24" in the ground, with
brass cap mkd: T 24 S R 4 W

¼ S 33
S 4

T 25 S R 4 W
1979

from which

A Fir 22" dia. bears N.23°E., 6 lks. dist. mkd. ¼ S33 BT.
A Fir 13" dia. bears S.52½°E., 40 lks. dist. mkd. ¼ S4BT.

Found OK, 1983 BLM Dependent Resurvey, Bishop & Rogers
(DCSO records Volume 46 Page 17808)

Fd. OK - Harvey Christensen - Dec. 1995 - M 123-25 A&B