

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 16

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>Original - Gordon & Gardner, Contract #52 dated Feb. 1855 (DCSO records Vol. 7 Page(s) 3046)</p> <p>-----</p> <p>Set ¼ sec. post from which A Cherry, 8" dia., bears S.2°W., 35 lks. A Maple, 18" dia., bears N.19°W., 14 lks.</p>
<p>O.F. Thiel - For: E.A. Davison - Jan. 1927 - FB 116 Pg 15</p> <p>-----</p> <p>Set Oak post by NW BT (Maple remarked) marked: A Cedar, 10" S.85°E., 30 lks.</p>
<p>Douglas Co. Surveyors Office -Milo E. Godfrey, Deputy - Vernon Tracy - Mike Stone - Feb. 1963 - C.S. File 53/9-27</p> <p>-----</p> <p>Found - 3/4" iron pipe driven flush with ground. 26" Maple, N.19°W., 9.2', opened several years ago, Fd. 2 old faces, upper & lower, surface rotted, no scribe marks found. Call on creek in gov't notes approx. 15' more than present dist. Cedar stake rotted off, cruiser's marks on small cedar near corner, fits good for line between section corners. No trace of Orig. SW BT.</p> <p>Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE T24S R4W ¼ S9/S16, 1963 6" I.Cedar, S.36°W., 17.3', mkd: ¼ S16 CS BT. 6" I.Cedar, N.45°E., 29.7', mkd: ¼ S9 CS BT.</p>
<p>Fd. & used in BLM dependent resurvey by James E. Jelly, Cadastral Surveyor, under Group #979, surveyed May/Sept. 1979 (DCSO records Vol. 42 Page(s) 16397-98)</p>
<p>Fd. & used in BLM dependent resurvey by Lance J. Bishop & James L. White, Cadastral Surveyor, under Group 1233, surveyed 10/84-1/1985 (DCSO records Vol. 42 Page(s) 18027)</p>
<p>Mark Smalley - Roseburg Forest Products - 8/11/1998 - C.S. File 65/20-40</p> <p>-----</p> <p>Found - 1963 DCSO BC/IP 11" Cedar, S.37°W., 17.3', good, healed face. 20" Cedar, N.45°E., 29.5', good, healed face. 28" Maple, N.19°W., 9.2', rotted center - hollow.</p> <p>New BT's-9" Fir, N.62°E., 12.5', "¼ S BT" 14" Alder, S.29°E., 27.3', "¼ S BT"</p> <p>Note - Mon. at fence cor. Fences run North, East & West.</p>

cont.

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by George M. Winter, Cadastral Surveyor under Group No. 2656, surveyed Sept./Nov. 2012 - (DCSO records Vol. 58 Page(s) 23007)

The ¼ sec. cor. of secs. 9 and 16, perpetuated by Smalley, in 1998, monumented with an iron post, 1½" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd. from which the remaining original bearing tree

- A maple, 30" dia., bears N.19°W., 9.2 ft., with axe marks visible on a hollowed blaze.
- and the remains of bearing trees mkd. by Godfrey, in 1963
- A cedar, 25" dia., bears N.44°E., 30.0 ft., with a healed blaze.
- A cedar, 12" dia., bears S.36°W., 17.2 ft., with no marks visible.
- and bearing trees mkd. by Smalley
- A fir, 13" dia., bears N.56¾°E., 12.1 ft., with a healed blaze.
- An alder, 15" dia., bears S.31°E., 27.8 ft., with a healed blaze.

Corner is located alongside a wood fence post, with fences extending N. and E.

NAD 1983 (2011)
Latitude: 43°29'24.40"N. Longitude: 123°10'38.75"W.