

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

<p>Original - Oscar F. Thiel, Contract #658, May 1896 (DCSO records Vol. 7 Page(s) 3071)</p> <p>-----</p> <p>Set a Fir post, 3' long, 3" sq., 24" in the ground for ¼ sec. cor. Marked ¼ S on W face from which</p> <p>    A Fir, 24" dia., bears N.13½°W., 37 lks., mkd: ¼ S BT.</p> <p>    A Fir, 18" dia., bears S.49°E., 16 lks., mkd: ¼ S BT.</p>
<p>James W. Byron, Deputy Co. Surveyor - Milo E. Godfrey - Clete Putman - March 1961 - C.S. File 49/124-71</p> <p>-----</p> <p>Found - Orig. 24", now 32" Fir stump, N.13½°W., 24.4', shows good scribing "¼ S BT"</p> <p>        Orig. 18" now 26" Fir, S.49°E., 10.6', shows old scar &amp; not old bark scribing "¼ S"</p> <p>Set - Brass cap at corner, mkd: COUNTY SURVEYORS OFFICE, 1961 ¼ S4 S3 T24S R4W</p> <p>        14" R.Fir, S.33°W., 36.6', scribed ¼ S3 CS BT.</p>
<p>Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - March/April 1963 - C.S. File 53/9-57</p> <p>-----</p> <p>Found - County Surveyor's brass cap, 1961 - OK</p> <p>        32" Fir stump, N.13½°W., 24.4', scribing still visible "¼ S".</p> <p>        Both trees marked in 1961 are down, blown over in Oct. 1962 windstorm.</p> <p>New BTs- 38" D.Fir, N.78°E., 33.6', mkd: ¼ S3 CS BT.</p> <p>        12" I.Cedar, S.57°W., 111.3', mkd: ¼ S4 CS BT.</p>
<p>Douglas Co. Surveyors Office - Larry E. Monrean &amp; crew - 11/26/1975 - C.S. File 57/39-18</p> <p>-----</p> <p>Found - 1961 CS BC in place, properly marked.</p> <p>        A Fir stump, 14" (now, bark gone, 32") dia., bears N.13½°W., 25.7', (rec. 24.4') scribed "¼ S BT.</p> <p>        A Fir, stump, 18 (now 28)" dia., bears S.53°E., 10.6' (rec. S.49°E.) Stump is out of ground, has good blaze.</p> <p>        A D.Fir stump, 38" dia., bears N.80°E., 33.6' (rec. N.78°E.) scribed "CS BT"</p> <p>        I.Cedar, 12" (now 19") dia., bears S.58½°W., 111.3' (Rec. S.57°W.) has good blaze, tagged.</p> <p>        Remains of stump bears S.33°W., 36.6', broke off near ground, (Rec. 14", R.Fir, S.33°W., 36.6')</p> <p>Renewal- A D.Fir, 12" dia., bears N.8°E., 203.9', scribed ¼ S3 CS BT.</p>

Cont.

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 4

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2168, Surveyed May/Nov. 2007 - DCS0 records Vol. 57 Page(s) 22608-9

-----  
The ¼ sec. cor. of secs. 3 & 4, remonumented by Byron, in 1961, Godfrey, in 1963, Monrean, in 1975, monumented with an iron post, 1¼" dia., firmly set, projecting 11" above ground, with brass cap (properly) mkd.

from which the remains of the orig. bearing trees  
A fallen, sawed, decayed fir stump, 25" dia. bears S.49°E. 10.6 ft., with scribe marks ¼ S visible on an opened blaze.

A sawed, decayed fir stump, 25" dia., bears N.13½°W., 25.7 ft., with scribe marks ¼ S BT visible on an open blaze. (Record, 24.4 ft.)

and remains of a bearing tree mkd. by Byron  
A decayed fir stump, size indeterminate, bears S.31°W., 38.0 ft., with no marks visible.

and remains of bearing trees mkd. by Godfrey  
A sawed, decayed fir stump, 46" dia., bears N.78¼°E., 33.3 ft., with a healed blaze.

A cedar, 37" dia., bears S.74½°W., 111.0 ft., with a healed blaze.

and bearing tree mkd. by Monrean  
A fir, 28" dia., bears N.6¾°E., 203.8 ft., with a healed blaze