

PRIMARY CORNER DESCRIPTION Cor. Secs. 26, 27, 34, & 35

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Gordon & Gardner, Contract #52 dated Feb. 1855 (DCSO records Vol. 7 Page(s) 3035)

Set post for cor. from which

- A W.Oak, 10" dia., bears N.51°E., 873 lks.
- A B.Oak, 20" dia., bears S.85°E., 833 lks.
- A B.Oak, 20" dia., bears N.67°W., 582 lks.
- A B.Oak, 16" dia., bears S.85°W., 400 lks.

BLM dependent resurvey by Charles E. Akin, Jr., Cadastral Surveyor, under Group #793, surveyed Aug. 1972 (DCSO records Vol. 36 Page(s) 14856)

Point for the cor. at proportionate dist.; there is no remaining evidence of the orig. corner.

T 24 S R 4 W  
S 27 S 26  
s 34 S 35  
1972

from which

- A Fir, 8" dia., bears N.75°E., 479 lks., mkd: T24S R4W S26 BT.
- A Fir, 15" dia., bears S.44 3/4°E., 369 lks., mkd: T24S R4W S35 BT.
- A Fir, 13" dia., bears S.17°W., 319 lks., mkd: T24S R4W S34 BT.
- A Fir, 35" dia., bears N.15°W., 133 lks., mkd: T24S R4W S27 BT.

BLM dependent resurvey by Lance J. Bishop & James L. White, Cadastral Surveyor, under Group 1233, surveyed Oct. 1984/Jan. 1985 (DCSO records Vol. 47 Page(s) 18022)

Point for the cor. at proportionate dist; there is no remaining evidence of the orig. corner.

From this point, the cor. established by Akin, in 1972, bears S.2°57'E., 0.33 chs. dist.

Remove the iron post, destroy the marks on the trees and at the true corner point

Reset the iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

T 24 S R 4 W  
S 27 S 26  
S 34 S 35  
1985  
1972

from which

- A Fir, 12" dia., bears N.73°E., 616 lks., mkd: T24S R4W S26 BT.

(Cont. next page)

PRIMARY CORNER DESCRIPTION Cor. Secs. 26, 27, 34 & 35

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

A Fir, 11" dia., bears S.33°E., 471 lks., mkd: T24S R4W S35 BT.  
A Fir, 22" dia., bears S.12 3/4°W., 398 lks., mkd: T24S R4W S34 BT.  
A Fir, 6" dia., bears N.17¼°W., 95 lks., mkd: T24S R4W S27 BT.

Fd & used in BLM dependent resurvey by Wayne L. Rogers & Boyd W. Peterson, Cadastral Surveyors, under Group #1314, surveyed April/May 1986 (DCSO records Vol. 48 Page(s) 18269)

Fd. Ok by H.Christensen, 12/95, M 123-21

Douglas County Surveyors Office - Randall Smith & Stephen Flause - 2/15/96 - C.S. 64/66 - 10

-----

Mon. Fd.- None ( postition of corner falls in old slash pile unable to locate BLM BC/IP with metal detector.

BT's Fd.- 8" dia. down and rotted D.Fir, we open and find scribe marks "BT" root crown, bears N.17¼°W., 62.7'.  
18" dia. D.Fir, with a fully healed single blaze, bears S.33°E., 310.9'.  
16" dia. D.Fir, with a fully healed single balze, bears N.73°E., 406.6'.  
27" dia. 1½' high D.Fir stump, with a fully healed blaze, bears S.12 3/4°W., 262.7'.

Mon. Set- 2 3/8" dia. Brass cap on a 1 3/8" O.D. by 32" long I.P. is 4" above ground, monument is surrounded by a 2' dia. mound of stone.

New BT's- 6" dia. D.Fir, double blazed and scribed "T24S R4W S27 CS BT", bears N.80½°W., 42.5'.  
10" dia. D.Fir, double blazed and scribed "T24S R4W S34 CS BT", bears S.24½°W., 95'.  
corner lies approx. 30' east of intersection of dirt roads.