

PRIMARY CORNER DESCRIPTION Cor. Secs. 26 & 35

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>Original - Gordon & Gardner, Contract #52 dated Feb. 1855 (DCSO records Vol. 7 Page(s) 3035)</p> <p>-----</p> <p>Set ¼ sec. post from which A B.Oak, 12" dia., bears S.58°W., 36 lks. A Laurel, 15" dia., bears N.25°W., 34 lks.</p>
<p>Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - June 1963 - C.S. File 53/9-94</p> <p>-----</p> <p>Found - Stump hole & remains of rotted Oak log, S.58°W., 23.8', fd. good reverse scribing "¼S" & portion of "BT" Old Laurel, down & shoved out of position, N.25°W., 22.4', could not determine exactly where it stood, opened & found portion of reverse scribing "4 & S"</p> <p>Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1963 T24S R4W S26/35 16" D.Fir, S.33°W., 12.6' Mkd: ¼ S35 CS BT. 10" D.Fir, N.12°W., 17.9' mkd: ¼ S26 CS BT.</p> <p>Note - Corner lies on nearly flat area on top of ridge at head of draw running south.</p>
<p>Fd. & used in BLM dependent resurvey by Charles E. Akin, Jr., Cadastral Surveyor, under Group #793, surveyed Aug. 1972 (DCSO records Vol. 36 Page(s) 14857)</p>
<p>BLM dependent resurvey by Lance J. Bishop & James L. White, Cadastral Surveyor, under Group 1233, surveyed Oct. 1984/Jan. 1985 (DCSO records Vol. 47 Page(s) 18022-23)</p> <p>-----</p> <p>From the ¼ sec. cor. monumented with an iron pipe, 2" dia., firmly set, projecting 6" above the ground, with properly marked brass cap. from which the trees mkd. by Godfrey A Fir stump, 18" dia., bears S.33°W., 18 lks., with healed blaze. A Fir, 17" dia., bears N.12°W., 27 lks., with healed blaze and new BT A Fir, 26" dia., bears S.13½°E., 179 lks., mkd: ¼ S35 BT.</p>
<p>Fd. & used in BLM dependent resurvey by Wayne L. Rogers & Boyd W. Peterson, Cadastral Surveyors, under Group #1314, surveyed April/May 1986 (DCSO records Vol. 48 Page(s) 18270)</p>
<p>FD. ok by Kris DeGroot, 8/2008 - 2008-0061A-G</p>