

PRIMARY CORNER DESCRIPTION Tsp Cor. (SE Cor. Sec. 36)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Gordon & Gardner, Contract #52 dated Feb. 1855  
(DCSO records, Volume 7 Page 3029)

-----  
Set post cor. of ranges 3 & 4 and T.24 & 25 S., from which  
A Maple 24" dia. bears N.21°W., 20 lks. dist.  
A Maple 8" dia. bears S.74°E., 93 lks. dist.  
A Fir 8" dia. bears S.72°W., 8 lks. dist.  
A Fir 10" dia. bears N.30°E., 32 lks. dist.

Bureau of Land Management Dependent Resurvey - Norman Price-  
Special Instructions dated April, 1940 - Survey, 1943  
(DCSO records, Volume 27 Page 11528-29)

-----  
Point for orig. cor. of Tps. 24 and 25, Rs 3 & 4 W.  
determined  
by reference to the record distances from the old SE., SW.,  
and NW. bearing trees.

At point for corner, set an iron post, 3 ft. long, 3" dia.  
28"

in the ground, with brass cap mkd:

T24S	
R4W	R3W
<u>S36</u>	<u>S31</u>
S1	S6
T25S	
1944	

from which  
A badly decayed Maple stump 16" dia. bears S.64°E., 93  
lks. on which no marks could be found.

The stump hole of a Fir bears S.72°W., 8 lks. which is  
the remains of an old bearing tree.

The fallen & badly decayed remains of a Maple 36" dia.  
bears N.21°W., 20 lks. dist., with only axe marks  
remaining to identify this as an old bearing tree.  
Local settlers verify this as an old bearing tree  
which they have seen the orig. inscription more  
than forty years ago.

A Fir 5" dia. bears N.60½°E., 85 lks. mkd. T 24 S R 3 W  
S 31 B T. (New BT)

A Fir 5" dia. bears S.58°E., 109 lks. mkd. T 25 S R 3 W  
S 6 B T. (New BT)

A Fir 50" dia. bears S.69°W., 333 lks. mkd. T 25 S R 4 W  
S 1 B T. (New BT)

An I.Cedar 14" dia. bears N.45¼°W., 133 lks. mkd T 24 S  
R 4 W S 36 B T. (New BT)

continued next page

PRIMARY CORNER DESCRIPTION Tsp Cor (SE Cor Sec 36)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy; Mike Stone - May 1963 - C.S. File 53/9-116

-----  
Found - 1944 Brass cap (buried under fill on W. side of logging railroad) Dig around & straighten up brass cap - Drive cedar stake alongside.  
18" D.Fir S.58°E., 71.9 ft. Cut open & found traces of scribing on badly rotted face.  
Stump of 50" Fir S.69°W., 219.8 ft. (across Calapooya from corner) Shows good scar.  
No trace remains of NE or NW bearing trees.  
Blaze & Rescribed: 18" D.Fir S.58°E., 71.9 ft. mkd. T25S R3W S6 CS BT.  
New BTs- 9" D.Fir N.82½°E., 66.1 ft. mkd: T24S R3W S31 CSBT  
10" D.Fir S.81°W., 34.5 ft. mkd: T25S R4W S1 CSBT.  
18" D.Fir N.4°W., 50.4 ft. mkd: T24S R4W S36 CS BT.

Greg Lang - For: Seneca Jones Timber Co. - April 2001 - M 138-6 & C.S. File 65/37-5c

-----  
Found - 1944 BLM brass cap, properly mkd.  
24" Fir bears S.81°W., 35.45 ft. Godfrey Set spike in the base of the tree & placed new tag.  
NW, NE, & SE BTs noted in the 1963 renewals are now stumps.  
New BTs- 13" Fir bears N.55°E., 19.5 ft. scribed "T24S R3W S31" "BT" Set spike in the base of the tree & placed new tag.  
12" Fir bears S.9°E. 156.5 ft. scribed "T25S R3W S6" "BT" Set spike in the base of the tree & placed new tag.  
18" Cedar bears N.28°W., 23.45 ft. scribed "T24S R4W S36" "BT" Set spike in the base of the tree & placed new tag.  
Set alum. post at corner.  
Set spike in the base of the tree & placed new tag.  
Note - Lies Easterly of Calapooya Creek & old RR bed.

DCSO-GIS Corner visitation - 5/13/2004 - Typed: 1/21/2011 - C.S. File 67/33-1

-----  
Monument - 3¼" BC/IP  
Comment - OK

FD. ok by Kris DeGroot, 8/2008 - 2008-0061A-G