

TOWNSHIP 24 RANGE 05 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 and 32

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Robert Elder, under Contract #31 dated April 7, 1853 (DCSO records Vol. 8 Page(s) 3116)

-----  
Set ¼ sec. post, from which  
A W.Oak 16" dia., bears N.67½°E., 108 lks.  
A W.Oak 12" dia., bears S.71°W., 81 lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; Clete Putnam - March 4-7, 1960 - C.S. File 49/124-33

-----  
Found - W.Oak now 25" N.69½°E., (Rec. N.67½°E.) 71.3 ft. Tree had been previously opened and grown over again, probably rotted inside, did not open.  
W.Oak now 24", S.73°W., (Rec. S.71°W.) 53.5 ft., cut open and found portions of reverse scribing, part of "B" and "T". Tree rotten inside.

Set Brass cap at cor. mkd: County Surveyors Office  
T 24 S R 5 W  
¼  $\frac{S\ 29}{S\ 32}$   
1960

Blaze and scribe new trees:  
10" W.Oak N.66°E., 58.0 ft. "¼ S29 CS BT"  
12" W.Oak S.45°W., 90.8 ft. "¼ S32 CS BT"  
Small creek approx. 50 ft. East of corner.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 5/6/2010 - C.S. File 67/31-9

-----  
Condition report  
Fd 1960 DCSO BC/IP and 3 live BTs.  
Orig. NE BT now down.  
Re-tag BTs

Fd as per 2010 report by D. Edwards, 1/2017 - M173-7