

TOWNSHIP 24 RANGE 05 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec Cor for 4, 5, 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder, under Contract #31 dated April 7, 1853 (DCSO records Vol. 8 Page(s) 3114)

Set post cor. to Secs. 4, 5, 8 and 9, from which
A Y.Oak 20" dia., bears S.60°E., 6 lks.
A Y.Oak 10" dia., bears S.40°W., 54 lks.
A Y.Oak 18" dia., bears N.62°W., 51 lks.
A Y.Oak 9" dia., bears N.1°E., 9 lks.

B.B. Irving, Douglas Co. Surveyor - Wit: W.S. Crear; N.E. Richardson; Ten Shallabarger - Feb. 12, 1929 - C.S. File 14/27

Location identified by 3 original BTs whose bearings and distances check original field notes.
Set a 6" Oak post for corner and blaze and scribed
A 20" Fir N.3°E., 93 lks. as a new BT in the NE quadrant
Original BTs, I do not disturb as all are in excellent condition.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; Clete Putnam - Aug. 1959 - C.S. File 49/124-7

Found - 20" now 24" Fir stump, as recorded by B.B.I. in 1929, I open and find good scribing "BT"
Orig. 20" now 40" B.Oak S.60°E., 4.0 ft., shows old scar, I do not open.
Orig. 18" now 36" B.Oak N.62°W., 33.7 ft. (I find should be 40.3 ft.) shows good scribing "S" on old face.
Orig. 10" now 20" partly rotted Oak stump S.40°W., 30 ft., shows reverse scribing "T"

Set Brass cap at cor. mkd: County Surveyors Office

T 24 S R 5 W
S 5 | S 4
S 8 | S 9
1959

New BTs -8" R.Fir bears S.51½°W., 14.1 ft. scribed S8 T24S R5W CS BT.
40" B.Oak S.60°E., 6.0 ft. scribed S9 T24S R5W CS BT.
8" R.Fir bears N.61°W., 8.0 ft. scribed S5 T24S R5W CS BT.
10" Laurel bears N.24°E., 28.5 ft. scribed S4 CS BT.
Corner is in fence corner, fences running West and North

continued next page

TOWNSHIP 24 RANGE 05 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec Cor for 4, 5, 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Fd. BC w/no accessories by W. Rogers, Feb. 2000 - M134-23
<p>Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 2/10/2000 - C.S. File 66/14-25 ----- Found - 1959 DCSO BC/IP, protrudes 12" above ground at fence corner. Fence lines run E, W, + N. No OBTs fd. 20" now 2 ft. high badly rotted D.Fir stump no blazes or scribing fd bears N.3°E., 61.4 ft. 1929 10" Madrone now young double trunked Madrone bears N.24°E., 28.5 ft. 1959 No other evidence of any 1959 BTs found. New BTs- 10" dia., Madrone bark scribed "T24S R5W S4 CS BT" bears N.23½°E., 28.1 ft. 25" dia., D.Fir single blazed and scribed "T24S R5W S4 CS BT" bears N.82½°E., 34.9 ft. 26" dia., D.Fir single blazed & scribed "T24S R5W S5 CS BT" bears N.62½°W., 51.4 ft. 45" dia., B.Oak single blazed & scribed "T24S R5W S5 CS BT" bears N.81°W., 64.0 ft. No trees South of corner, open pastures.</p>
Fd. Ok by Neil Hibbs, June 2005 - M146-21
<p>Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 7/12/2007 - C.S. File 67/21-41 ----- Fd as per record</p>