

TOWNSHIP 24 RANGE 05 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec Cor for 4 & 5; 32 & 33, T23-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2345-46)

Set Post, cor. to secs. 32, 33, 4 and 5, from which
A W.Oak 60" dia., bears N.2°W., 468 lks.
A W.Oak 28" dia., bears N.9 3/4°E., 818 lks.
A Y.Oak 16" dia., bears S.23 1/2°E., 571 lks.
A Y.Oak 24" dia., bears S.13 1/4°W., 833 lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey and Clete Putnam - Dec. 15, 1959 - C.S. File 49/42-32

Found - Orig. 28" now 40" W.Oak N.9 3/4°E., 539.9 ft., shows good scars. I do not open.
Orig. 60" now 24" W.Oak N.2°W., 308.9 ft., shows good scars. I open center, rotted, no scribing found.
Orig. 16", now down and mostly rotted Oak, S.23 1/2°E., 376.9 ft., shows good scribing, reverse, on trunk section, "BT W"
Orig. SW BT, not found.

Set Brass Cap mkd: County Surveyors Office
S 32 | S 33 T23S R5W
S 5 | S 4 T24S R5W
1959

New BTs -6" W.Oak bears N.57°E., 12.0 ft. scribed S33 T23S R5W CS BT.
12" R.Fir bears S.33°W., 19.7 ft. scribed S5 T24S R5W CS BT.
9" R.Fir bears S.57°E., 32.2 ft. scribed S4 T24S R5W CS BT.
28" B.Oak bears N.10°W., 60.0 ft. scribed S32 T23S R5W CS BT.
3-Way fence corner bears N.28°W., 30 ft., more or less.

Fd. OK, Oct. 1969, DCSO, V.Tracy, C.S. File 54/16-67

Fd. OK, July 1990, Land Partition, 1990-0035

BLM dependent resurvey by Wayne Rogers & Bryan Seibold, Cadastral Surveyors, under Group #1832 surveyed July - Oct. 1997 - (DCSO recs. Vol. 53 Pg(s) 20271-2)

The cor. of secs. 4, 5, 32 & 33, perpetuated by Byron, in 1959, from orig. evidence no longer in existence, monumented with an iron post, 1 1/2" diam., firmly set, projecting 8" above ground, with brass cap mkd. continued next page

TOWNSHIP 24 RANGE 05 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5; 32 & 33, T23-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

COUNTY SURVEYORS OFFICE
T23S R5W
S 32 | S 33
S 5 | S 4
T24S R5W
1959

from which the remains of bearing trees mkd. by Byron
A fir, 25" diam., bears S.57°E., 48 lks., with healed double blaze.
A sawed fir stump, 25" diam., bears S.33¼°W., 29½ lks., with healed double blaze.
An oak, 35" diam., bears N.10¼°W., 91 lks., with healed double blaze.
and new bearing trees
A fir, 28" diam., bears N.71¼°E., 97 lks., mkd. T23S R5W S33 BT.
A fir, 27" diam., bears S.5½°W., 38½ lks., mkd. T24S R5W S4 BT.

The corner is located E., 0.25 chs., from a dirt road, 20 lks. wide, extending N.60°E. and S.70°W., and E., 0.05 chs. from a woven wire fence, extending N. and S.

Fd. OK by W. Rogers, Feb. 2000 - M134-23
Fd. BC by ODOT, 9/2009 I5-025B
Fd. BC 4/2013 by Todd Patterson, M165-18
Fd. As per 1997 BLM survey by D Edwards 3/2020 - M176-69