



TOWNSHIP 24 RANGE 05 POINT IDENTIFIER # 440100

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec 34; & 3 T25-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

New Accessories -

DCSO Brass cap in concrete "TRUCKS 1980", bears  
N.73°E., 561.4'

3/4" I.R. (521+8.80 RT) in southerly RW fence,  
bears N.77½°E., 453.9'.

3/4" I.R. (41+65.78 RT) in southerly RW fence,  
bears N.89¼°W., 605.6'.

Corner lies in an open field 65' southerly of Driver Valley  
RD. and 125' westerly of a small pond.

Douglas Co. Surveyors Office - John Pike - Pat Crawford -  
9/9/2004 - C.S. File 67/6-21

Found - Brass cap monumented fd. (1957) broken off on top of  
ground in small hayfield. Rest of iron pipe bent  
but in place where it goes straight down.

48" now 49" W.Oak with large previously opened blaze  
bears S.35½°W., 551.6 ft. (1957)

All new accessories from 1997 renewal in place.

New - Referenced plumb position of broken off pipe.

Set - 2" brass cap on 30" iron pipe t" below ground, mkd:

DOUGLAS CO SURVEYORS OFFICE

T24S R5W

¼ S 34  
S 3

T25S R5W

RESET

2004

Witness post "NEARBY SURVEY MARKER" bears North 58.4  
ft. in R/W fence.

Decl. 17½°E.