

PRIMARY CORNER DESCRIPTION W 1/4 Cor for Sec 30 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 8 Page(s) 3129)

Set ¼ sec. post, from which
A Fir 14" dia., bears N.66°W., 18 lks. dist.
A Fir 12" dia., bears S.13°E., 61 lks. dist.

Cor. Fd. and used by Whipple in GLO resurvey, Contract #622 dated June 23, 1893 (DCSO records Vol. 8 Page 3234)

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; Clete Putnam - August 27, 1959 - C.S. File 49/83-26

Found - Orig. 14" now 40" R.Fir N.66°W., 11.9 ft. I open and find good scribing "4"
Orig. 12" now 30" Fir, now down, shows old scar, S.13°E., 40.3 ft.
1" angle Iron corner marker set by Haines at corner (No record)

Set Brass cap alongside 1" angle iron, marked:
County Surveyors Office

West ¼
S 30 T24S
R7W R6W
1959

New BTs -30" Laurel bears S.50°E., 43.2 ft. scribed W¼ S30 CS BT
5" Cedar bears S.16°E., 71.2 ft. scribed W¼ S30 CS BT.

BLM dependent resurvey by Joseph S. Gawron under Group #464 surveyed May/June 1962 (DCSO records Vol. 31 Page(s) 13115)

The ¼ sec. cor. of sec. 30 only, which has been perpetuated with a Douglas County survey mark, an iron post, 1½" dia., firmly set, with 1959 brass cap.

from which the remains of the original bearing trees
A down Fir 24" dia., bears S.13°E., 61 lks. dist. with a burned face.

A Fir snag 38" dia., bears N.66°W., 18 lks. mkd. ¼ S BT. and trees mkd. by the County Surveyor

A Madrone 32" dia. bears S.50°E. 66 lks. mkd W ¼ S30 CS BT

A Cedar 6" dia., bears S.16°E., 108 lks. dist. mkd. W ¼ S30 CS BT.

and new bearing trees (Cont. Next Page)

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 100240

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. Sec. 30 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Madrone 17" dia. bears N.85°E., 146 lks., mkd. ¼ S30 BT.
A Fir 6" dia., bears S.64°E., 128½ lks., mkd. ¼ S30 BT.
I mark USBLM on the brass cap.

Douglas Co. Surveyors Office - Gary L. Langlitz, Deputy -
Peter Earle, Gary Commons, crew - 7/25/1974 - C.S. 57/2-5

Found - 1" x 1" T-Iron with Haines copper washer attached
and 1959 DCSO brass cap alongside.

from which:

Orig. 14" now 40" D.Fir stump bears N.66°W., 11.9
ft., no scribing visible.

Orig. 12" now 30" D.Fir, down, bears S.13°E., 40.3
ft., no marks visible.

A 32" Madrone marked in 1959, bears S.50°E., 43.2
ft., scribing visible on partially healed blaze.

A 5" now 10" Cedar bears S.16°E., 71.2 ft. well
healed. (1959)

A 17" Madrone, now a stump, bears N.85°E., 96.4 ft.
scribing "¼ S30 BT" visible on unhealed blaze.
(1962)

A 6" now 8" D.Fir, now down, bears S.64°E., 84.8 ft.
scribing "¼ S30 BT" visible on unhealed blaze.
(1962)

At this time, the markings "USBLM" noted in the official gov.
survey notes, do not appear on the Co. Surveyor's brass cap.
We do not mark any new bearing trees.
Corner lies 20 ft. SE of a dirt road.

Mark Smalley, Roseburg Resources - 7/2002 - C.S. File 65/44-8

Found - 1959 IPBC

OBT 40" Rotted stump N.66°W., 11.9'

OBT 30" D.Fir Down & rotted S.13°E., 40.3'

32" Madrone, rotted stump, no marks visible S.50°E.,
43.2'

19" R.Cedar, healed, good, S.16°E., 71.2'

17" Madrone, stump, visible scribing, N.85°E., 96.4'

6" Fir, stump, no marks visible, S.64°E., 84.8'

1"x1" "T" iron, S.47°W., 0.5'

New - 17" D.Fir bears N.86°W., 44.1' scribed "¼ S25 BT"

10" D.Fir bears N.1°W., 39.2' scribed "¼ S25 BT"

12" D.Fir bears S.76°E., 20.7' scribed "¼ S30 BT"

Note - Corner is 20' SE of Rd. #24-6-19.1. Road now rocked.
Compass decl. 18°E.