

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #577, dated July 18, 1891 (DCSO records Vol. 8 Page(s) 3179)

Set Fir post, 4 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on N. face, from which
A Fir 65" dia., bears N.18°30'E., 25 lks. mkd. ¼ S BT.
A Fir 48" dia., bears S.17°30'E., 34 lks. mkd. ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage, crew - Oct. 2, 1972 - C.S. File 52/102-20

Found - 48" D.Fir, now stump, S.17½°E., 22.4 ft. Old bark scribe visible ¼S BT.
65" D.Fir now 66", N.18½°E., 16.5 ft. Badly burnt face. Part of "B" visible.

Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 6 W

¼ $\frac{S}{S}$ $\frac{4}{9}$
1972

New BTs -6" Cedar S.49°E., 20.0 ft. scribed ¼ S9 CS BT. Note:
Face bearing and distance.
16" D.Fir N.65°W., 33.0 ft. scribed ¼ S4 CS BT.

David Edwards - For: Roseburg Resources - July 2018 - M174-53

Fount - Brass cap
OBTs are gone.
1972 DCS cedar is down.
A 30" dia., 8' tall fir stump bears N.65°W., 33.0'
Both with healed blaze.
Set - A 6' steel post 2' east.
New BT - A 23" dia. Fir scribed "¼ S9 BT" bears S.77°W., 5.4'