

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 8 Page(s) 3147)

Set ¼ sec. post, from which
A Fir 8" dia., bears S.60°E., 119 lks. dist.
A Fir 11" dia., bears N.55°W., 55 lks. dist.

G.G. Stewart, DCS - Wit: Leatherwood; Baird; Bartrum; and McHugill - March 27, 1922 - Vol. 3 Page 115

Set Iron pipe. Marked:
24" Fir N.42°W., 63.0 ft.
30" Fir S.66°W., 63.0 ft.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - May 8, 1969 - C.S. File 52/102-2

Found - 1¼" I.P. set by Stewart in 1922.
4 3/4" I.R. dropped inside. I.P. is broken and rusted through.
24" now 24" W.Fir N.42°W., 63.0 ft., only decayed remains, no scribe found.
30" now 30" D.Fir S.66°W., 63.0 ft., now sawed stump, scribe marks visible on burned and unhealed blaze.

Set Brass cap at cor. point 1" I.P. mkd:
County Surveyors Office
T 24 S R 6 W
¼ S33|S34
1969

New BTs -8" D.Fir N.41°W., 37.3 ft. mkd. ¼ S33 CS BT.
10" D.Fir S.19°E., 11.4 ft. mkd. ¼ S34 CS BT.
Reset unrecorded I.R. alongside. This cor. lies at fence cor. E and S.

Fd. Ok by Les Roberts - March 2000 - M134-38

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 9/25/2006 - C.S. File 67/14-28

Found - 1969 BC/IP not found. Several short pieces of very rusted 1¼" iron pipe were fd. in search area. I.Rod noted in 1969 renewal not fd.
10" D.Fir now 14" dia., 20 ft. tall D.fir snag, healed single blaze visible bears S.12½°E., 11.4 ft. (rec. S.19°E., 11.4 ft.) 1969 BT
continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias	Description
Alias	Description
Alias	Description
Alias	Description

8" D.Fir now 22" dia., x 6 ft. tall W.Fir stump, partially healed blaze w/fragmentary scribe marks visible bears N.39°W., 37.3 ft. (rec. S.19°E., 11.4 ft.) 1969 BT

30" sawed fir stump now rotting 3 ft. tall stump burned face visible, no scribe seen, bears S.66°W., 64.0 (rec. S.66°W., 63.0 ft. fits better as face measurement) 1922 BT

No trace of NW BT fd. (Rec N.42°W., 63.0 ft) 1922 BT

New - Set 2½" BC mkd: COUNTY SURVEYORS OFFICE
T24S R6W
S 33|S 34
2006

on 1¼" O.D. iron pipe 30" in length. Projects 8" above ground. Monument was reset by a distance-distance intersect from remaining 1969 accessories. Could not match rec. bearings to 1969 accessories possibly due to magnetic attraction of fences at corner position.

26" dia., D.Fir double blazed & scribed "¼ S34 CS BT" bears N.69°E., 49.3 ft.

12" dia., Oregon Ash double blazed & scribed "¼ S34 CS BT" bears S.39°E., 40.5 ft.

23" dia., I.Cedar double blazed & scribed "¼ S33 CS BT" bears S.37°W., 13.6 ft.

Note - Approx. 350 ft. southerly of Hwy 138 on gentle north facing slope. Approx 1.3 ft. north of dilapidated fence corner with fences extending South & East. Compass decl. 16½°E.