

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 8 Page(s) 3151)

Set post, cor. to secs. 9, 10, 15 and 16, from which
A Y.Oak 24" dia., bears N.1½°W., 750 lks. dist.
A Fir 18" dia., bears N.7½°E., 894 lks. dist.
A Cedar 12" dia., bears S.69°W., 424 lks. dist.
No tree near in section 15.

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #577, dated July 18, 1891 (DCSO records Vol. 8 Page(s) 3169)

The Sec. cor. for 9, 10, 15 and 16, Post gone. From the bearing trees standing, I reestablish the same by setting a Cedar post, 4 ft. long, 4" sq., 24" in the ground, mkd. T24S S10 on NE.; R6W S15 on SE.; S16 on SW.; and S9 on NW. faces with 4 notches on S. and 3 notches on E. edges, from which, the original bearing trees are as follows:

- A Fir 18" dia., bears N.7½°E., 894 lks. dist. mkd. T24S R6W S10 BT.
- An Oak 24" dia., bears N.1½°W., 750 lks. dist., marked, but rotted away.
- A Cedar stump 24" dia., bears S.69°W., 424 lks. dist., mkd. S BT.

The tree has recently been chopped down and made into posts destroying balance of marks. Take new bearing trees as follows:

- A Cedar 10" dia., bears S.10°30'E., 156 lks. dist. mkd. T24S R6W S15 BT.
- A Cedar 12" dia., bears S.84°10'W., 181 lks. dist. mkd. T24S R6W S16 BT.
- A Cedar 12" dia., bears N.75°25'W., 160 lks. dist. mkd. T24S R6W S9 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; S.A. Bilow - Aug. 1958 - C.S. File 49/83-18

Found - 12" now 40" Cedar, down, previously opened, shows good scribing "T2S", S.84°10'W., 129.5 ft. (record) I find 123.0 ft.
10" now 40" dead Cedar, shows good scar. I do not open, S.10½°E., 103.0 ft.
3" x 48" steel section fo plough frame bears S.40°W., 4.0 ft. said to be at corner.

(Cont. Next Page)

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 6 W
S 9 | S10
S16 | S15
1958

New BTs -12" Apple tree, N.61½°E., 126.4 ft. scribed S10 T24S R6W CS BT.
22" double W.Oak S.88°W., 199.7 ft. scribed S16 T24S R6W CS BT.
16" W.Oak S.86°E., 255.6 ft. scribed S15 T24S R6W CS BT.
3" Cedar S.21°W., 57.7 ft. scribed CS BT.

Fd. and used in BLM resurvey by C.Albert White and Norman McDonald, Cadastral Surveyors in 1963, (DCSO records, Vol. 32 Page 13312)

Fd. and used in BLM resurvey by Berry and Akin, Cadastral Surveyors & G.Baughman L.S. #536 in a 1973-75 survey (DCSO records, Vol. 37 Pages 15246-47)

Mark Smalley - For: Roseburg Resources - 8/1998 - M 129-12

Found - 1958 County Brass cap on iron pipe.
14" Apple tree, N.61½°E., 126.4 ft., rotten center.
27" double W.Oak S.88°W., 199.7 ft., healed.
22" W.Oak S.86°E., 255.6 ft., healed.
Scribed- 13" Cedar, N.60°W., 100.0', "S9 BT"
Set - 5/8"x48" iron rod & alum. cap, East 10.0' marked "RM ← 10'".

Found OK by K. DeGroot, June 2004 - M146-6