

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 8 Page(s) 3149)

-----  
Set ¼ sec. post, from which  
A Y.Oak 8" dia., bears N.18°E., 25 lks. dist.  
A Y.Oak 10" dia., bears S.18½°W., 57 lks. dist.

Briggs - 1888 - Vol. 1 Page 117

-----  
Set post by Old BT.

Floyd Cole - June 1915 - Field Book 37 Pg. 48; Vol. 2 Pg. 270

-----  
Renew cor. from orig. BTs. Tree S.18½°W. standing, other tree down. Set a Cedar post 4x4x42", from which  
A B.Oak 16" S.32 3/4°E., 59 lks.  
W.Oak 24" N.87°W., 43 lks.  
Fir 36" S.42½°W., 77 lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; S.A. Bilow, crew - Sept. 2, 1958 - C.S. File 49/83-8

-----  
Found - Old Cedar stake (4"x4") set by Cole, 1915, with scribing "CS ¼S" plainly visible.  
Remains of orig. BT, S.18½°W., 37.6 ft. Axe marks and part of old face visible. No scribing visible.  
Oak, uprooted and down, with face chopped open. Center portion entirely rotted away. The stump hole for this tree is N.87°W., 28.4 ft. from cor.  
B.Oak now 20" dia., S.32 3/4°E., 38.9 ft. This tree has been chopped open and center portion is entirely rotted away.  
Fir now 42" dia., S.42½°W., 50.8 ft. This tree has been chopped open and the face badly charred but faint traces of scribing are visible. No letters or numbers legible.

Set Brass cap at cor. mkd: County Surveyors Office  
T 24 S R 6 W  
¼  $\frac{S\ 22}{S\ 27}$   
1958

Blaze and scribe following trees:  
20" D.Fir S.41°W., 12.0 ft. mkd. ¼ S27 CS BT.  
14" I.Cedar N.5°E., 15.4 ft. mkd. ¼ S22 CS BT.

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Corner is in East and West fence line.

BLM resurvey by Wayne L. Rogers, Cadastral Surveyor, under Group #969, surveyed April/May 1979 (DCSO records Vol. 42 Page(s) 16491-2)

-----

The ¼ sec. cor. of sees. 22 & 27, perpetuated & recorded by Cole, in 1915, from orig evidence no longer in existence, further perpetuated by Byron, in 1958, monumented with an iron post, 1¼" dia., firmly set, projecting 16" above ground, with brass cap (properly) mkd.  
from which the remains of BTs mkd. by Cole  
    An oak, 24" dia., bears S. 33½°E., 59 lks. with healed double blaze.  
    A fir, 44" dia., bears S.42½°W., 77 lks. with healed double blaze.  
    A root hole, bears N.87°W., 44 lks. with a down oak alongside, 18" dia., with axe marks visible on decayed blaze.

and the remains of BTs mkd. by Byron  
    A cedar, 18" dia., bears N.1¾°E., 24 lks. with healed double blaze.  
    A sawed fir stump, 20" dia., bears S.41°W., 19 lks. with scribe marks ¼ S27 CS BT visible on open double blaze.

Fd. BC, 38" Oak (S.33½°E., 38.9') & 44" Fir S.42½°W., 50.8;) both w/healed blaze- by D. Edwards, 10/2005 - M148-79

Brent Knapp - For: Aaron Swan - 12/2024 - M184-46 A&B

-----

Found - Brass cap (prop mkd)  
    39" Oak S.33°W., 39' with healed blaze  
    44" Fir S.42°E., 51' with healed blaze