

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Robert Elder & Henry Gile, Deputy Surveyors, under Contract #31 dated April 7 1853 (DCSO rec Vol 8 Pg 3151)

-----  
Set ¼ sec. post, from which  
A Fir 36" dia., bears S.14°E., 30 lks. dist.  
A Fir 24" dia., bears N.33°W., 56 lks. dist.

BLM resurvey by Daniel Berry and Charles Akin Cadastral Surveyors, and Glenn Baughman, LS #536 under Group #'s 826 and 856, Surveyed Sept. 1973/Aug. 1975 (DCSO records Vol. 37 Page(s) 15247-48)

-----  
The ¼ sec. cor. of secs. 10 and 15, perpetuated by person(s) unknown, monumented with a wooden post, 4" sq., firmly set, projecting 10" above ground, from which the remains of the original bearing tree:

A sawed Fir stump 48" dia., bears S.14°W., 30 lks no marks visible on opened blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

1/4  $\frac{S}{S}$   $\frac{10}{15}$   
T 24 S R 6 W  
1973

from which new bearing trees

A Fir 10" dia., bears N.79°E., 53 lks., mkd. ¼ S10 BT.

A Fir 6" dia., bears S.63°W., 20 lks., mkd. ¼ S15 BT.

Reset wooden post alongside iron post.

From this point, a local corner established by Roseburg Lumber Co., in 1973, bears N.28°W., 0.05 chs., monumented with an iron pipe, 1½" dia., firmly set, projecting 28" above ground, from which bearing trees mkd. by Roseburg Lumber Co.:

A Fir 10" dia., bears N.77½°E., 24 lks. dist., no marks visible on open blaze.

A Fir 4" dia., bears S.19°W., 12 lks. dist., no marks visible on open blaze.

Cor. Fd. and used in BLM survey by Wayne L. Rogers, Cadastral Surveyor, under Group #1623, surveyed Sept/Oct. 1991 (DCSO records, Vol. 50 Page 19228)

FD OK by Ken Hoffine, April 1996 - M 123-66

Fd. OK by C. Sweeden, Sept. 2002 - 2002-0038 A & B

Found OK by K. DeGroot, June 2004 - M146-6

FD. BC, 2 BTs, 3 stumps and 1 IP by C. Sweeden, 2/2012 - M163-27

-----cont. next

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 15

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Daniel A Renton, Minister-Glaeser Surveying - Garrett Finch & Crew - For: US Department of Interior, BLM - Mean Mustard & Galagher Canyon 1- Task A -Aug. 2023 - M185-5 A-D

-----  
Found - 3¼" BLM brass cap (properly mkd), 0.3' above ground from which:  
An east/west wire fence bears North 2'  
A north/south barb wire fence bears East 0.4'  
A 1½" iron pipe bears N.28°W., 3.3' (1973 Roseburg Lumber Co.  
A 12" Fir bears S.42°W., 7.2' to BLM brass cap with healed double blaze and sign (1973 record to Roseburg iron pipe, S.19°W., 12 lks.)  
A 24" Fir bears S.63°W., 14.0' with healed blaze and sign (1973)  
A 38" stump (4' high) bears S.14°W., 19.5' (orig.)  
A 17" rotted stump bears N.68°E., 14.6' to BLM brass cap (1973 record to Roseburg iron pipe, N.77½°E., 24 lks.)  
A 13" rotted stump (6 high) bears N.72°E., 35.1' (1973)  
Established the following -  
A 7" Fir bears N.83°E., 7.3' mkd: ¼ S10 BT.  
(Set chaining nail at side center, BT signs on front and back and painted red band for existing & new BTs)