

PRIMARY CORNER DESCRIPTION Sec. Cor. 34 & 35; 2 & 3, T25-6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, Contract #31 dated April, 1853  
(DCSO records, Volume 8 Page 3131)

-----  
Set post cor. to secs. 34, 35, 2 & 3, from which  
A Y.Oak 11" dia. bears S.16°E., 15 lks. dist.  
A Y.Oak 12" dia. bears S.68½°W., 91 lks. dist.  
A Y.Oak 12" dia. bears N.39°W., 89 lks. dist.  
A Y.Oak 15" dia. bears N.26°E., 74 lks. dist.

Bureau of Land Management Dependent Resurvey, Stephen  
Albright; Jack Bowder - June 1972 - (DCSO records, Volume  
36 Page 14996-97)

-----  
There is no remaining evidence of the original corner.  
Set an iron post 28" long 2½" dia. 22" in the ground, with  
brass cap marked:

T 24 S R 6 W  
S 34 | S 35  
S 3 | S 2  
T 25 S  
1972

from which  
A Fir 11" dia. bears S.29½°E., 75 lks. dist. mkd. T25S  
R6W S2 BT.  
A Fir, 7" dia. bears S.41°W., 107 lks. dist. mkd. T25S  
R6W S3 BT.  
A Fir 12" dia. bears N.23½°W., 247 lks. dist. mkd. T24S  
R6W S34 BT.

Fd Ok by R. Dolan, 9/93 - C.S. 64/97-3  
Found Ok by Douglas Co. Surveyors Office - Randall W. Smith  
& Stephen J. Flause - 1/29/1998 - C.S. File 64/79-9

Mark Smalley - For: Roseburg Forest Products - 10/14/2003 -  
C.S. File 65/48-44

-----  
Found - 1972 BLM IPBC  
15" Fir S.29½°E., 49.5 healed.  
20" Fir S.41°W., 70.6 healed.  
17" Fir N.23½°W., 163.0 healed.  
New - 12" Fir S.43°E., 13.8' scribed "S 2 BT"  
Dec. 20°

DCSO-GIS Corner visitation - 7/1/2004 - Typed: 1/25/2011 -  
C.S. File 67/33-1

-----  
Monument - BC/IP 2.5"  
Comment - Ok