

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 cor. for secs. 14 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 8 Page(s) 3145)

Set ¼ sec. post, from which
A W.Oak 15" dia., bears N.16°E., 165 lks. dist.
A W.Oak 6" dia., bears N.1°W., 192 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; S.A. Bilow, crew - Aug. 1958 - C.S. File 49/83-17

Found - Orig. 6" now 16" W.Oak, center rotted, N.1°W., 126.7 ft. I open and find faint scribing "C 1"
Orig. NE BT, shows old face previously opened, now badly rotted. No scribing found.

Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 6 W
¼ S15 | S14
1958

New BTs -21" B.Oak bears S.88½°W., 78.0 ft. scribed ¼ S15 CS BT.
12" B.Oak bears N.21½°E., 93.8 ft. scribed ¼ S14 CS BT.

(Note: Per BLM Dec. 10, 1991, "no evidence of BTs. Cap laying out of ground. Cor. proportioned on cadastral survey")

BLM Resurvey by Wayne L. Rogers, Cadastral Surveyor, under Group #1623, surveyed Sept/Oct. 1991 (DCSO records Vol. 50 Page(s) 19226-27)

Point for the ¼ sec. cor. of secs. 14 & 15, at proportionate dist; there is no remaining evidence of the original corner. Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.

T24S R6W
1/4
S 15 | S 14
1991

from which
A Fir 28" dia., S.0½°E., 139 lks. dist. mkd. ¼ S14 BT.
A Fir 13" dia., S.74½°W., 216 lks. dist. mkd. ¼ S15 BT.
Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

Fd. Brass cap, Sept. 1995 by D. Bentz - C.S. File 63/165-4
FD. BC & 2 BTs, by C. Sweeden, 2/2012 - M163-27
Fd as per M163-27 5/2018 (filed 6/2021) by M Schulze, M179-44