

| Alias | Description |
|-------|-------------|
| _____ | _____       |
| _____ | _____       |
| _____ | _____       |
| _____ | _____       |

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2387)

- 
- Set post, secs. 1, 2, 35 and 36, from which
- A Laurel 14" dia., bears N.74½°E., 100 lks.
  - A Fir 36" dia., bears S.60°E., 98 lks.
  - A Fir 50" dia., bears S.78°W., 64 lks.
  - A Fir 12' dia., bears N.73°W., 124 lks.

Corner tied in resurvey by Wm. Thiel, contract #310 dated Nov. 30, 1978 (DCSO records, Vol. 6 Page 2394)

(Did find 36" Fir S.60°E., down.)

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12642-43)

-----

The Sec. Cor., the rotted remains of old stake, 30" long, 4" sq., mkd. S36 on NE., T24 S1 on SE.; S2 on SW., and R6W S35 on NW. face, tied to cor. of fences, extending E., W., & S. At the corner point

Set an iron post, 3 ft. long, 2" dia., 27" in the ground, with brass cap mkd:

T23SR6W  
S35\*S36  
S 2\*S 1  
T24S  
1943

from which

- A Fir 22" dia., bears N.62½°E., 98 lks. dist., mkd. T23S R6W S36 BT.
- A Fir 20" dia., bears S.43½°E., 26 lks. dist., mkd. T24S R6W S1 BT.
- A Fir 30" dia., bears S.33½°W., 32 lks. dist., mkd. T24S R6W S2 BT.
- A Fir 30" dia., bears N.23°W., 74 lks. dist., mkd. T23S R6W S35 BT.

Douglas Co. Surveyors Office - L.E. Monrean and A.V. Cangie, crew - April 22, 1975 - C.S. File 57/21

-----

Found - 1943 GLO brass cap, properly marked.

- A 22" now 25" Fir bears N.62½°E., 64.2 ft. (Rec. 64.7 ft.) Good blaze.
- A 20" now 24" Fir S.43½°E., 17.2 ft., good blaze.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor for 35 & 36; 1 & 2, T23-6

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

A 30" Fir stump bears S.33½°W., 20.2 ft. (Rec. 21.1 ft.) Part of blaze remains.  
A 30" now 35" Fir bears N.24½°W., 45.0 ft. (Rec. N.23°W., 48.8 ft.) Good blaze.  
New BT - A D.Fir 11" bears S.68°W., 11.0 ft. scribed T24S R6W S2 CS BT.

Found OK by D. Edwards, May 2002 - M140-13

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2308, Surveyed April/July 2010 - (DCSO records Vol. 57 Page(s) 22829)

-----  
The cor. of secs. 1, 2, 35, & 36, on the S. bdy. of the Tp., perpetuated by the Douglas Co. Surveyor's Office in 1975, subsequently perpetuated by person(s) unknown, monumented with an iron post, 2" dia., firmly set, projecting 12" above ground, with a brass cap (properly) mkd.  
from which the remains of an original bearing tree  
A roothole bears N.74½°E., 66.0 ft., downhill of which is a portion of a down, burnt, decayed madrone snag, size indeterminate, with no marks visible.  
and the remains of BTs mkd. by Gould, Gawron, and Eggen  
A fir, 35" dia., bears N.62½°E., 64.7 ft., with a healed blaze.  
A sawed, decayed fir stump, 26" dia., bears S.43½°E., 17.2 ft., with a healed blaze.  
A sawed, decayed fir stump, size indeterminate, bears S.33½°W., 21.1 ft., with scribe marks BT visible on an open blaze.  
A fir, 40" dia., bears N.23°W., 44.9 ft., with a healed blaze. (Record, 48.8 ft.)  
and a BT mkd. by the Douglas County Surveyor's Office  
A fir, 23" dia., bears S.68½°W., 11.1 ft., with a healed double blaze.  
and a bearing tree mkd. by person(s) unknown  
A fir stump, 4" dia., bears S.58¼°E., 7.4 ft., downhill of which is a down fir snag, 4" dia., with scribe marks S1 BT visible on an open blaze and a metal tag mkd. LS 2339 2002.  
and a new bearing tree  
A fir, 6" dia., bears S.54¼°E., 92.1 ft., mkd. T24S R6W S1 BT.  
Corner is located in a down, woven and barbed wire fence line extending E. and W., 25 ft. E. of a seasonal creek, 2 ft. wide, course S. 70°E.