

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 173100

PRIMARY CORNER DESCRIPTION M.C. on S. Bdy Section 31

Alias <u>868010</u>	Description <u>M.C. Left bank Umpqua River</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Original - Dennis Hathorn, Deputy, Contract #73 dated June 8, 1857 (DCSO records, Vol. 8 Page 3194)</p> <p>-----</p> <p>Cedar 12" dia., mark same for meander post, left bank, from which</p> <p>    An Oak 10" dia., bears S.10°E., 24 lks. dist.</p> <p>    A Cedar 12" dia., bears N.45°W., 47 lks. dist.</p>
<p>Ronald Geisler, LS #1988, for: Champion International - Feb. thru March 1983 - M 93-79</p> <p>-----</p> <p>Set - 2½" Alum. cap set on a 7/8" x 36" Iron pipe, on west bank of Umpqua River near high water line.</p> <p>    4" Fir bears N.60°W., 9.1 ft. scribed X BT.</p> <p>    24" Fir bears N.6°E., 104.0 ft. scribed MC S31 BT.</p> <p>Note: No BTs available south of line.</p>
<p>Fd.&amp; used on BLM dependent resurvey by Bryan S. Seibold &amp; Wayne Rogers, Cadastral Surveyors, under Group #1862, surveyed Sept.-Dec. 1997 - (DCSO record Vol. 53 Page(s) 20302)</p>
<p>Douglas Co. Surveyors Office - Crew: Stephen Flause &amp; Jeff Lorsung- 3/5/2019 (Filed 11/17/2021) - C.S. File 67/50-15</p> <p>-----</p> <p>Found - A 2½" dia., alum. cap on a 3/4" I.D. IP, cap is properly mkd. Cap is projecting 10", pipe is rusted and cracker 2" above ground. 1983</p> <p>    A 38" dia., D.Fir with FHSB, bears N.4¼°E., 105.0 ft. (rec N.6°E., 104.0') 1983</p> <p>    A 22" dia., D.Fir with fully healed high-low blaze; bears N.54°W., 9.1 ft. (rec. N.60°W., 9.1') 1983</p> <p>    BLM records</p> <p>        38" Fir N.4¼°E., (158 lks) 104.3 ft</p> <p>        22" Fir N.58°W., (13½° lks) 8.9 ft.</p> <p>New - Found mon. broken off at crack. A 5/8"x30" IR driven into IP to proj. 10" alum cap and IP set over iron rod.</p> <p>Note - Lies 50' east of Tye Access Rd centerline and west of the Umpqua River.</p>
<p>1</p>