

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Plumb position of monument is perpetuated as found because hand written notes from 1971 from C.S. File 49/41 state that brass cap was set at the original record distances from both orig. BTs and at the orig. record bearing from the original SW. bearing tree, and current measurements indicate the plumb position of the monument is as described in the hand written notes in C.S. File 49/41. Plumb position of brass cap monument is reference out, monument is removed from ground and "RESET 1987" is added to cap. Monument is reestablished plumb and set flush with ground (because of location of mowed lawn) at the above mentioned referenced position.

New Accessory:

The NE. corner of the concrete foundation of the R.C. Rice house at 497 Indian Bend Road, bears S.16°W., 22.1 ft.

Monument is in lawn in back yard of a private residence and is at N. edge of a bench above Umpqua River flood plain.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 10/17/2000 - C.S. File 66/16-53

Found - 1971 DCS0 BC/IP flush w/ground in yard.
Both OBTs now stumps to be removed by property owner.
24" now 31" dia., W.Oak with a fully healed single
blaze bears N.72°E., 59.2 ft.
NE Corner of concrete foundation of house bears
S.16°W., 22.1 ft.
New - 11" dia., W.Oak double blazed & scribed "¼ S30 CS BT"
bears N.13°W., 29.1 ft.
Note - Orig. SW BT opened & good scribing fd. "¼S"