

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 200640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 5 and 6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3215)

Set ¼ sec. post, from which
A Cedar 18" dia., bears N.75°W., 37 lks. dist.
A Fir 20" dia., bears N.62°E., 5 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - Sept. 1960 - C.S. File 49/41-40

Found - Orig. 20" now 30" R.Fir, N.62°E., 3.3 ft. I open and find good scribing "BT"
Orig. NW. BT, now down and mostly rotted, checks bearing and distance to stump section.
Also find 1/2" Iron pipe, 1.0 ft. South.
Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 7 W
¼ S 6 | S 5
1960

New BTs- Rescribe now 30" R.Fir, N.62°E., 4.1 ft. "¼S5 CS BT"
8" W.Fir bears S.48°W., 9.3 ft. "¼ S6 CS BT"

BLM Resurvey by C. Albert White, Cadastral Surveyor and Donald R. Beck, Surveying Technician, Under Group #515, Surveyed June/Oct. 1963 - (DCSO records Vol. 32 Page(s) 13485)

The ¼ sec. cor., perpetuated and recorded by Byron in 1960, monumented with an iron post, 1" dia., firmly set, protruding 18" above the ground with brass cap mkd. in 1960, from which the original bearing trees:

A down Fir 37" dia., bears N.62°E., 7 lks. dist., 5 lks. dist. to face, mkd. BT on partially opened blaze.
Remarked ¼ S5 CS BT by Byron. (Rec., 5 lks.)
A rotted Cedar stump bears N.75°W., 37 lks. dist.

and a bearing tree mkd. by Byron:
A Fir 8" dia., bears S.49°W., 14 lks. dist. mkd. ¼ S6 CS BT.

and new bearing trees:
A Fir 10" dia., bears N.6¼°E., 77 lks. dist. mkd. ¼ S5 BT.
A Cedar 24" dia., bears N.40°W., 71 lks. dist. mkd. ¼ S6 BT.

Survey by Mark Smalley - For: Scott Timber Co. - Sept. 1996 -M 125-67

Found - 1960 County BC/IP. Cor. is 1 ft. East of N-S fence
(Cont. Next Page)

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 200640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found - 18" Cedar N.75°W., 24.42 ft., rotten, down. (OBT)
30" Cedar N.40°W., 46.86 ft., part healed.
14" Fir N.62°E., 3.3 ft., broken stub.
14" Fir N.6¼°E., 50.82 ft., healed.
New BTs- 7" Fir S.10°E., 10 ft. "¼ S BT"
10" Fir S.67°W., 8.2 ft. "¼ S BT"