

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 240300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3217)

Set ¼ sec. post, from which
 An Oak 12" dia., bears N.40°W., 50 lks. dist.
 An Oak 12" dia., bears S.40°W., 50 lks. dist.

H.L. Eppstein, County Surveyor - Wit: Rudolph Ritzman; J.C. Clayton; Ernie Short - April 1926 - C.S. File 14/36 and Vol. 4 Page 3

Set corner on proportional distance between the section corner. From this location found an old tree which was right for distance and bearing but no scribe marks could be found. Set ½ buggy axle for corner. Also stake, 4" x 4" x 4'. Marked new BTs as follows:
 Fir 8", N.42°W., 22.6 ft.
 Fir 12", S.72°30'E., 13.0 ft.

Douglas Co. Surveyors Office - John M. Powell - 12/1970 (added 7/19/2021) - C.S. File 49/41-65

Reported as not found
Area logged very heavy hazel & poison oak brush.

Survey by George Grubb - For: Patricia Cagle - Feb. 1982 - M 91-27

Set 5/8" x 30" I.R. with a yellow plastic cap, stamped "BAUGHMAN TECH SERV", 26" in ground, from which new BTs bear:
 8" D.Fir scribed "¼ S29 BT" bears S.38°W., 17.1 ft.
 6" D.Fir scribed "¼ S20 BT" bears N.3°W., 50.6 ft.
Lying next to the tree in sec. 20, I found the root wad and 20 ft. of trunk of an 8" Fir, down and badly rotted. Inspection revealed a double face and scribe marks "S ¼ BT" visible. Impossible to determine where this tree originally stood. A thorough search was made for the 1/2" buggy axle but it was not found.