

PRIMARY CORNER DESCRIPTION North 1/4 Cor. Sec. 4 only, T25-7

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>Original - Wm. R. Whipple, under Contract #622 dated June 23, 1893 (DCSO records, Volume 8 page 3230)</p> <p>-----</p> <p>Set a post 3 ft. long, 3" sq., 24" in the ground mkd. 1/4 S on N face, from which</p> <p style="padding-left: 40px;">A Fir 12" dia., bears N.37°E., 24 lks. mkd. 1/4 S BT.</p> <p style="padding-left: 40px;">A Fir 30" dia., bears S.67°E., 24 lks. mkd. 1/4 S BT.</p>
<p>Bert W. Udell, H.E. Taylor, witness - Sept, 1948 C.S. 40/114</p> <p>-----</p> <p>Found - "1/4 S" scribed on remains of 12" Fir. This tree is rotten and broken.</p> <p style="padding-left: 40px;">30" Fir at S.67°E., is in good shape. Scars show plainly.</p> <p>I Set stake at corner and marked new tree:</p> <p style="padding-left: 40px;">34" Fir at N.52°E., 30.5 ft. from corner, mkd. "CSBT CS 1/4".</p>
<p>Doug. County Surveyors Office - V. R. Tracy; Michael Stone; Jack Heritage - April 13, 1966 - C.S. File 54/10</p> <p>-----</p> <p>Found - 34" Fir N.52°E., 30.5 ft. turned out, shows "CS BT" scribe on unhealed face.</p> <p style="padding-left: 40px;">Possible orig. 12" Fir N.37°E., 15.8 ft. shattered stump, no scribing found.</p> <p style="padding-left: 40px;">Orig. SE BT, now turned out stump, out of position.</p> <p>Set Brass cap at 1/4 cor. mkd: County Surveyors T24S Office, 1966 T25S<sup>R7W</sup> 1/4 <sup>X</sup>/<sub>S 4</sub></p> <p style="padding-left: 40px;">New BTs - 5" D.Fir S.63°E., 92.2 ft. mkd. 1/4 S4 CS BT.</p> <p style="padding-left: 40px;">14" W.Fir N.8°E., 64.8 ft. mkd. 1/4 S4 CS BT.</p>
<p>Ronald Rice - For: Roseburg Resources Co - Jan 2011 - M162-1</p> <p>-----</p> <p>Found - 1966 Douglas County brass cap</p> <p style="padding-left: 40px;">33" W.Fir bears N.8°E., 64.8' - healed face</p> <p style="padding-left: 40px;">24" D.Fir bears S.22 1/4°W., 59.1' - scribing visible (BLM tagged 2006)</p> <p style="padding-left: 40px;">11" D.Fir bears S.84 1/2°W., 44.7' - scribing visible (BLM tagged 2006)</p> <p style="padding-left: 40px;">1/4 Corner section 33, T24S R7W bears N.89°59'E., 213.18' per 1983 BLM records</p> <p>New BT - 21" D.Fir bears N.82°W., 16.7' - blazed, scribed "X BT"</p>
<p>continued next page</p>

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 337100

PRIMARY CORNER DESCRIPTION North 1/4 Cor. Sec. 4 only, T25-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by Timothy J Moore, Cadastral Surveyor and Robert H. Browning, Survey Tech, under Group No. 2300 surveyed May 2006 - (DCSO records BLM Plat 2011-2 & Vol. 57 Page(s) 22690)

[www.co.douglas.or.us./survmaps/CORNERS/Cadastral/Plats/2407W](http://www.co.douglas.or.us./survmaps/CORNERS/Cadastral/Plats/2407W)

-----  
The ¼ sec. cor. of Sec. 4 only, on the N. bdy. of T25S R7W recovered by Jelley and Rogers in 1979, monumented with an iron post, 1¼" dia., firmly set, projecting 9" above the ground, with brass cap (properly) mkd.

from which the remains of a bearing tree mkd. by Tracy

A fir, 31" dia., bears N.8°E.. 64.7 ft., with a healed blaze.

and new bearing trees

A fir, 10" dia., bears S.22¼°W., 59.1 ft., mkd. ¼ S4 BT.

A fir, 23" dia., bears S.84½°W., 44.9 ft., mkd. ¼ S4 BT.