

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Sec Cor for 14 & 15 only (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3200)

Marked a Chinquapin 5" dia., for cor. secs. 14, 15, 22 and 23, from which

- A Chinquapin 6" dia., bears S.35°E., 35 lks. dist.
- A Fir 36" dia., bears N.45°E., 34 lks. dist.
- A Fir 30" dia., bears S.68°W., 23 lks. dist.
- A Fir 36" dia., bears N.74°W., 50 lks. dist.

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 8 Page(s) 3271-72)

The cor. to secs. 14, 15, 22 and 23, which is a Chinquapin 8" dia., mkd. T24S S14 on NE.; R7W S23 on SE.; S33 on SW.; and S15 on NW.; with 3 notches on S. and 2 notches on E. sides, from which

- A Fir 36" dia., bears N.45°E., 34 lks. dist. mkd. T24S R7W S14 BT.
- A Chinquapin 10" dia., bears S.35°E., 35 lks. dist. mkd. T24S R7W S23 BT.
- A Fir 30" dia., bears S.68°W., 23 lks. dist., mkd. T24S R7W S22 BT.
- The NW. BT, being gone, A Dogwood 6" dia., bears N.72°W., 15 lks. dist. which I mark T24S R7W S15 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - June 10, 1958 - C.S. File 49/41-14

- Found - Orig. 8" now 16" Chinquapin at corner.
Orig. 36" now 48" stump, good scribing visible "BT", N.45°E., 24.6 ft.
Orig. 6" now 12" Dogwood N.72°W., 9.9 ft., scribe marks visible.
Orig. 30" now 30" snag, S.68°W., 15.2 ft., burned and rotted.

Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 7 W
S 15 | S 14
S 22
1958

New BTs- 24" R.Fir N.50°W., 19.0 ft."T24S R7W S15 CS BT."
7" R.Fir N.48°E., 63.7 ft. scribed T24S R7W S14 CS BT.

(Cont. Next Page)

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Sec Cor for 14 & 15 only (South)

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Survey by Bruce Shaner Engineering - For: U.S. Bureau of Land Management - Jan. 8, 1973 - M 49-6

Found 16" Chinquapin corner tree, stump, rotten center. In center of corner tree, I place the DCSO brass cap mkd. in 1958. (Brass cap did bear N.76°W., 1.4 ft. from corner tree.) from which a:

- 32" D.Fir, orig. BT stump, scribing visible, bears N.40°E., 22.4 ft. (Rec. 48" dia., N.45°E.)
- 12" D.Fir, scribing visible, bears N.48°E., 63.7 ft.
- 30" D.Fir, orig. BT, snag, burned and rotted, bears S.68°W., 15.2 ft.
- 30" D.Fir, face visible, bears N.50°W., 20.7 ft.
- 12" Dogwood, orig. BT, now rotted stump, bears N.72°W., 9.9 ft.
- Rotted D.Fir, root stump, possible orig. BT, bears N.79°W., 33.0 ft.

Fd. and used in BLM resurvey by Daniel Berry and Charles Akin Cadastral Surveyors, under Group # 807 Surveyed June/July. 1973 (DCSO records Vol. 37 Page(s) 15292-93)

- Fd. Ok by C. Sweeden, Aug. 1997 - M124-61
- Fd. OK by C. Sweeden, July 1999 - M131-79
- Fd. OK by C. Sweeden, Feb. 2001 - M136-63
- Fd. Ok by C. Sweeden, 8/2005 - 2005-0084 A&B