

PRIMARY CORNER DESCRIPTION So. 1/4 cor. for Sec. 35 only, T23-7

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 6 Page(s) 2516)

 Set a Fir post for the ¼ sec. cor., from which
 A Chinquapin 6" dia., bears N.45°E., 7 lks. dist.
 A Fir 24" dia., bears S.70°E., 66 lks. dist.

BLM resurvey by Joseph S. Gawron, Cadastral Surveyor, under Group #405, surveyed June 1958 - (DCSO records Vol. 30 Page(s) 12589-90)

 1/4 Cor. is monumented with a partially decayed Fir post, 2 x 2 ins., scribe marks not legible, from which the remains of the original bearing trees:

A Chinquapin stool bears N.45°E., 7 lks. dist.
 A sawed Fir stump 36" dia., bears S.70°E., 66 lks. dist.
 mkd. BT. At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 23 S R 7 W
 ¼ S 35
 T 24 S
 1958

from which

A Chinquapin 8" dia., bears N.64°E., 9 lks. dist. mkd. ¼ S35 BT.

A Fir 9" dia., bears N.63½°W., 108 lks. dist. mkd. ¼ S35 BT.

Fd. OK, July 1980 by C. Guile - M 79-52

Mark Smalley - For: Roseburg Resources - Sept. 2002 - M141-7

 Found - 1958 Cadastral brass cap on an iron pipe
 23" Fir N.63½°W., 71.3' healed face.

36" Rotten Fir stump S.70°E., 43.5'
 New - 13" Fir N.76°W., 23.4' scribed "¼ BT"
 12" Fir N.9°E., 16.0' scribed "¼ BT"