

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 14 only (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3196)

Set post cor. secs. 13, 14, 23 and 24, from which
A Maple 12" dia., bears N.10°E., 25 lks. dist.
An Alder 12" dia., bears N.25°W., 28 lks. dist.
A Fir 60" dia., bears S.30°E., 35 lks. dist.
A Fir 15" dia., bears S.48°W., 36 lks. dist.

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 8 Page(s) 3267-68)

At the cor. to secs. 13, 14, 23 and 24, where I find two of the original bearing trees standing, and which I re-establish as follows:

Set a stone 16x12x4 ins., 10" in the ground for cor. to secs. 13, 14, 23 and 24, marked with 3 notches on S. and 1 notch on E. edges, from which
A Fir 10" dia., bears N.41°E., 62 lks. dist. mkd. T24S R7W S13 BT.
A Fir 70" dia., bears S.30°E., 35 lks. dist. mkd. T24S R7W S24 BT.
A Fir 20" dia., bears S.48°W., 36 lks. dist. mkd. T24S R7W S23 BT.
A Maple 8" dia., bears N.21°W., 97 lks. dist. mkd. T24S R7W S14 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - June 3, 1958 - C.S. File 49/41-9

Found - Orig. 15" now 36" Fir stump S.48°W., 23.8 ft. Parts of old scribing visible "S 1" on exposed face.
Old and partly rotted Fir snag checks bearing and distance for original SE. BT.

Distance between corners checks record 83.2 ft. Also good for bearing. (Secs. 13 & 14 and Secs. 23 & 24)

Set brass cap for corner mkd: County Surveyors Office

T24S R7W
S14|S13
S23
1958

Chiseled and "+" on West face of small section 4 ft. x 5 ft. x 10 ft. sandstone bears S.52°E., 9.3 ft.

New BTs- 10" W.Fir bears N.23½°E., 46.5 ft. scribed S13 T24S R7W CS BT.

13" Cedar bears N.60½°W., 64.2 ft. scribed S14 T24S R7W CS BT. (Cont. Next Page)

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 14 only (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. OK, Jan. 1964 by M. Godfrey, DCSO - C.S. File 49/41-54

Fd. and used in BLM resurvey by Daniel Berry and Charles Akin Cadastral Surveyors, under Group # 807 Surveyed June/July. 1973 (DCSO records Vol. 37 Page(s) 15288-89)

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 2/17/98 - C.S. File 64/79-32

Found - 2½" dia., brass cap on a 1½" O.D. iron pipe, protrudes 12" above ground. 1958
Two stones are found along Easterly edge of BC/IP.
15" now 36" dia. 4 ft. high rotted D.Fir stump with a fully healed blaze, bears S.48°W., 23.8 ft. (Agrees with rec.) OBT
10" now 30" dia. 3 ft. high rotted D.Fir stump scribing found "24" bears N.41°E., 40.9 ft. (Agrees with rec.) 1893
13" now 25" dia. R.Cedar with a fully healed double blaze, bears N.61½°W., 64.2 ft. (Rec. N.60½°W., 64.2 ft. 1958
10" now 33" dia. W.Fir, with a fully healed double blaze, bears N.23½°E., 46.5 ft. (Agrees with rec.) 1958
Chiseled "+" on sandstone from 1958 NOT FOUND
New BTs- 10" dia. Myrtle, double blazed and scribed "T24S R7W S13 CS BT" bears N.83°E., 9.6 ft.
9" dia. Alder, double blazed and scribed "T24S R7W S13 CS BT" bears N.34½°E., 27.0 ft.

Fd. Ok by C. Sweeden, 8/2005 - 2005-0084 A&B
Fd. ok by D. Edwards 7/2007 - M153-56