

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Sec Cor for 1, 2, 11 and 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3198-99)

Set post cor. secs. 1, 2, 11 and 12, from which
An Oak 18" dia., bears S.5°W., 70 lks. dist.
An Oak 24" dia., bears S.70°E., 8 lks. dist.
An Oak 24" dia., bears N.10°E., 295 lks. dist.
An Oak 18" dia., bears N.84°W., 218 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - April 10, 1958 - C.S. File 49/41-6

Found - Orig. SE. BT, now snag, shell only.
Orig. NW. BT, alive and good condition, open face shows good scribing.
Orig. SW. and NE. BTs, alive. I do not open.
Set Brass cap at cor. mkd: County Surveyors Office

T	24	S	R	7	W
S	2	S	1		
S	11	S	12		
1958					

New BTs- 14" forked B.Oak bears N.11°E., 6.5 ft. scribed T24S R7W S1 CS BT.
48" B.Oak bears S.3°W., 47.7 ft. scribed T24S R7W S11 CS BT.
7" W.Oak bears S.55½°E., 31.8 ft. scribed T24S R7W S12 CS BT.
15" W.Oak bears N.81°W., 109.0 ft. scribed T24S R7W S2 CS BT.

Fd. OK July 1980 by Charles Guile - M 79-52

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Jan. 25, 1988 - C.S. File 62/50-7

Found - 1958 DCSO brass cap on a 1" I.P. mowed off with 7" of iron pipe attached to BC. Remaining I.P. protrudes 7" out of ground with top bent West. Bearing and distances of accessories taken to plumb position of bent iron pipe.
18" x 13" x 3" stone found laying flat on E. edge of plumb position of bent I.P. near surface. (source unknown)
18" now 54" dia. B.Oak with fully healed blazes bears S.3°W., 47.7 ft. (Orig. rec. S.5°W., 46.2 ft.) Orig. BT, rescribed in 1958)

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 1, 2, 11 and 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Orig. SE. BT is gone, a depression in ground is found near bearing and distance.
24" now 62" dia. B.Oak with a burnt out face, no scribing seen, bears N.10°E., 196.6 ft. (Rec. N.10°E., 194.7 ft., possible face measurement.)
18" now 36" dia. Oak with a previously opened now burnt and rotted blaze, no scribing found, bears N.84°W., 145.5 ft. (Rec. N.84°W., 143.8 ft., possible face measurement.) Orig. BT.
14" now 19" dia. B.Oak with a fully healed double blaze bears N.11°E., 6.5 ft. (agrees w/rec.)
7" now 12" dia. W.Oak with a fully healed double blaze, bears S.55½°E., 31.8 ft. (agrees w/rec.)
15" now 19" dia. W.Oak with a fully healed double blaze, bears N.81°W., 108.5 ft. (Rec. N.81°W., 109.0 ft.)
Set a 2 3/8" brass cap on a 1¼" outside dia. x 31" long, I.P. is set flush with ground, mkd. "Douglas County Surveyors T24S S2 S1 S11 S12 R7W 1988."
1958 Brass cap with 7" of I.P. set 5" below ground along S. edge of new brass cap/iron pipe.
18" x 13" x 3" stone, undisturbed while setting new B.C., lies along E. edge of new brass cap/iron pipe.
Corner position is perpetuated at the plumb position of bent top iron pipe. This position is referenced and above monuments set.
Corner lies on a westerly sloping hillside.

Fd. Ok by D. Edwards - 12/97 M 127-78

Fd. & used on BLM Dependent resurvey by Dale Bedell, Cadastral Surveyor, under Group #1728, surveyed May 1994-April 1995 - (DCS0 records Vol. 52 Page(s) 19835-6)

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - July 16, 2014 - C.S. File 67/41-28

Found - A 2¾" dia. brass cap (properly mkd) on a 1" I.D. IP is set approx flush with the ground. 1988
The 18x13x3" stone is fd as described in the renewal.
The remains of the 1958 BC monument are not looked for.
Evidence of the 3 OBTs fd in 1988 remains but all 3 have fallen down. All bearings and distances (measured to fd centers of root-crowns) agree with 1988 record.

continued next page

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Sec Cor for 1, 2, 11 and 12

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

The SW OBT is now a fallen and rotting 54" dia., B.Oak with fully healed blazes.
The NE OBT is now a fallen and out of position rotting 60" B.Oak with blazes as described.
The NW OBT is now a fallen and almost completely rotted away Oak. No blaze evidence remains.
The 3 new in 1958 BTs are fd as described in 1988.
Bearing and distance agree with the 1988 record. These BTs are now sized as follows.
The NE'ly B.Oak measures 24"
The SE'ly W.Oak measures 18"
The NW'ly W.Oak measures 26"
New - A 55" dia., B.Oak scribed "T24S R7W S11" "CSBT" on a double blaze; bears S.47°W., 99.7 ft.
Note - Monument is on SW slope in open grassland with scattered Oaks.
Compass decl. 15½°E.