

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; & 6 of T24-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors,
under Contract #31 dated April 7, 1853 (DCSO records Vol. 8
Page(s) 3127)

Set ¼ sec. post, from which
A Laurel 14" dia., bears S.67°W., 80 lks. dist.
A Fir 10" dia., bears S.60°E., 110 lks. dist.

GLO resurvey by Orville N. Eggen, Cadastral Surveyor, under
Group #244, surveyed May/Aug. 1957 (DCSO records Vol. 30
Page(s) 12619)

Point for the ¼ sec. cor., at proportionate distance; there
is no remaining evidence of the original corner.
Set an iron post, 30" long, 2" dia., 18" in the ground, with
brass cap mkd:

T 24 S
 ¼
R 7 W | R 6 W
S 1 | S 6
1957

from which
A W. Fir 15" dia., S.78°E., 52 lks. dist., mkd. ¼ S6 BT.
A Fir 12" dia., S.76°W., 88 lks. dist., mkd. ¼ S1 BT.

BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under
Group #244, surveyed April/May 1964 (DCSO records Vol. 32
Page(s) 13492-93)

Point for the ¼ sec. cor. of secs. 1 and 6, at proportionate
distance; there is no remaining evidence of the original
corner.

From this point, the ¼ sec. cor., erroneously reestablished
by Eggen, in 1957, bears South, 0.14 chs. dist., set, marked
and witnessed as described in the official record. I remove
the iron post, and at the corner point
Reset the iron post, 28" long, 2½" dia., 24" in the ground,
with brass cap mkd:

T 24 S
R 7 W | R 6 W
 ¼
S 1 | S 6
1957

from which the bearing trees mkd. by Eggen, in 1957
A Fir 12" dia., bears S.49½°E., 59½ lks. dist., with a
healed blaze.
A Fir 14" dia., bears S.65°W., 95 lks. dist., with a
healed blaze.

(Cont. Next Page)

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 700640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; & 6 of T24-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Resurvey by Dale Bedell - May 1992 thru April 1993 under group # 1637. (DCSO records Vol. 51 Pg. 19541)

Point for the 1/4 sec. cor. of secs. 1 and 6, at proportionate distance, there is no remaining evidence of the original corner.

Set - A stainless steel post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.

T24S
R7W R6W
1/4
S 1 | S 6
1993

from which bearing trees mkd. by Brooks -

A Fir, 15" dia., bears S.58°E., 111 lks. dist., with healed blaze.

A Fir, 21" dia., bears S.30 3/4°W., 70 lks dist., with healed blaze.

Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

NOTE - From this point, the ¼ sec. cor. of secs. 1 and 6 erroneously reestablished by Brooks in 1964 bears S.67°04'00"E., 0.530 chs. dist., monumented with an iron post, 2½" dia., firmly set, projecting 2" above the ground, with brass cap marked marked and witnessed as described in the official record. Amend the brass cap to read "T24S R7W R6W ¼ S1 S6 1957 AMENDED 1993" and reset monument flush with the ground.

Mark Smalley - for: Roseburg Forest Products - Dec. 6, 1996
- C.S. 65/15-6D

Mon. Fd.- 1993 Cad. I.P.B.C.
Bt's Fd.- 16" Fir, S.58°E., 73.3' good healed face
21" Fir, S.30°W., 46.3' good healed face - does not face corner

New Accessories -
13" Cedar, N.62°W., 16.4' scribed "¼ S BT"
13" Cedar, S.82°E., 21.4' scribed "¼ S BT"

continued next page

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 700640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; & 6 of T24-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

David Edwards, For: Dory Construction - 2/2019 - M175-23

Found - BLM brass cap
14" dia., 6 ft tall fir stump with healed blaze
bears S.58°E., 73.3'
25" fir with healed blaze bears S.30¾°W., 46.2'
13" cedar with 1996 RFP tag & healed blaze bears
S.82°E., 21.4'
14" cedar with 1996 RFP tag & healed blaze bears
N.62°W., 16.4'