

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 31; & 36, T24-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 8 Page(s) 3298)

Set Hemlock post 40" long, 5" dia., 18" in ground for ¼ sec. cor. East bdy., sec. 36, from which
A Yew 8" dia., bears N.58°E., 32 lks. dist.
A Yew 10" dia., bears N.35°W., 32 lks. dist.

BLM Resurvey by James E. Jelly; Harvey E. Wofford; Wayne L. Rogers, Cadastral Surveyors, under Group #'s 926 and 958 - Surveyed Aug. 1977/April 1979 - (DCSO records Vol. 42 Page(s) 16436-37)

The 1/4 sec. cor., determined at record distance from the remains of the original bearing trees:

A root hole bears N.58°E., 32 lks. dist., with a down Yew alongside 8" dia., with illegible scribe marks visible on decayed blaze.

A root hole bears N.25°W., 32 lks. dist., with a down Yew alongside, 9" dia., no marks visible. (Rec. N.35°W.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 24 S
1/4
R 9 W R 8 W
S 36 S 31
1979

from which new bearing trees:

A sawed Cedar stump 40" dia., bears S.63°E., 69 lks. dist., mkd. ¼ S31 BT.

A sawed Fir stump 48" dia., bears S.33°W., 73 lks. dist. mkd. ¼ S36 BT.

Corner is located in open logged area.