

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 31 and 32

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3366)

Set a sandstone 18 x 16 x 8 ins., 12" in the ground for 1/4 sec. cor. mkd. 1/4 on West face, from which
A Fir 40" dia., bears N.57°E., 14 lks. dist. mkd. 1/4 S BT.
A Fir 30" dia., bears N.20°W., 30 lks. dist. mkd. 1/4 S BT.

Survey by Howard W. Johnstone, LS #498 - For: Roseburg Lumber Co. - Nov. 10, 1983 - M 95-41

Found - 3/4" Iron pipe and 18 x 16 x 8 sandstone.
64" Fir N.57°E., 9.2 ft. No marks.
36" Fir N.20°W., 19.8 ft. Bark scribe, down.
New BT - 5" Fir N.42°W., 3.3 ft.

Tony Hostetter - For: Weyerhaeuser Co. - Nov. 2013 - M167-6

Found - 3/4" iron pipe described by Johnstone in 1983 (M95-41).
GLO BTs present but out of position.
New BTs- 8" Fir, scribed "S31 1/4 BT" BT tag, bears; N.28°41'E. 21.5' to spike.
8" Fir, scribed "S31 1/4 BT" BT tag, bears; N.44°00'E. 31.5' to spike.
10" Hem, scribed "S31 1/4 BT" BT tag, bears; N56°19'E. 45.8' To spike.