

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19, 20, 29 and 30

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3369-70)

-----

Set a post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 19, 20, 29 and 30 marked ,T24S S20 on NE.; R8W S29 on SE.; S30 on SW.; and S19 on NW. faces, with 2 notches on S. and 5 notches on E. edges, from which

- A Fir 36" dia., bears S.27°E., 69 lks. dist. mkd. T24S R8W S20 BT.
- A Fir 36" dia., bears S.13°E., 74 lks. dist. mkd. T24S R8W S29 BT.
- A Fir 40" dia., bears S.28°W., 25 lks. dist. mkd. T24S R8W S30 BT.
- A Fir 12" dia., bears N.23°W., 68 lks. dist. mkd. T24S R8W S19 BT.

BLM corner remonumentation by Harold D. Corbin, Cadastral Surveyor, under Group #'s 350 and 427, Surveyed June 1959 - (DCSO records Vol. 30 Page(s) 12615-16)

-----

The sec. cor., determined at record distance from the remains of the original bearing trees:

- A stump hole with roots and bark of a Fir tree, bears N.27°E., 69 lks. dist. (Rec. brg. S.27°E.)
- A downed Fir 40" dia., bears S.13°E., 74 lks. dist. with scribe marks BT visible on partially opened blaze.
- A Fir 60" dia., bears S.28°W., 25 lks. dist. with healed blaze.
- A rotted Fir stump bears N.23°W., 68 lks. dist.

At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 24	S R 8 W
<u>S 19</u>	<u>S 20</u>
S 30	S 29
1959	

from which

- A Hemlock 10" dia., bears N.32½°E., 57 lks. dist. mkd. T24S R8W S20 BT.
- A Hemlock 6" dia., bears S.19½°E., 42 lks. dist. mkd. T24S R8W S29 BT.
- A Hemlock 7" dia., bears S.48½°W., 36 lks. dist. mkd. T24S R8W S30 BT.
- A Hemlock 13" dia., bears N.37°W., 49 lks. dist. mkd. T24S R8W S19 BT.

(Cont. Next Page)

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 200300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19, 20, 29 and 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. and used in BLM resurvey by C. Albert White;, Cadastral Surveyor and Donald R. Beck, Surveying Technician - under Group #427, Surveyed July/Aug. 1962 - (DCSO records Vol. 32 Page(s) 13333)

Tony Hostetter - For: Weyerhaeuser Co - 3/2006 - C.S. 65/58-7  
-----

Found - 1959 BLM brass cap as described in Vol. 30 Pg 12615.  
60" fir stump, face evident, bears; S.28°W., 16.5 ft  
18" hemlock, 1959 BT, bears S.19½°E., 26.7 ft  
(Record: 27.7 ft) placed WEYCO tag.

20" hemlock stump, scribing visible, bears N.37°W.,  
32.3 ft.

New BTs- 16" hemlock, scribed "S29 NW BT" tagged, bears  
S.84°E., 35.8 ft to spike placed below scribing.  
8" fir, scribed "S19 SE BT", tagged, bears N.80°W.,  
4.0 ft to spike placed below scribing.  
12" fir, scribed "S19 ¼ BT" tagged, bears N.74°W.,  
13.0 ft to spike placed below scribing.