

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 301700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33 T23-8 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2555-56)

Sandstone 18x16x5 ins., 12" in ground for the cor. to secs. 32 and 33, marked with 4 notches on E. and 2 notches on W. edges, from which

A Hemlock 12" dia., bears N.7½°E., 38 lks. dist. mkd. T23S R8W S33 BT.

A Hemlock 6" dia., bears N.65°W., 35 lks. dist. mkd. T23S R8W S32 BT.

A Hemlock 24" dia., bears S.75°W., 50 lks. dist. mkd. T23S R8W S32 & 33 BT.

BLM remonumentation by Joseph S. Gawron Cadastral Surveyor, under Group # (?) surveyed 1963 - (DCSO records Vol. 33 Page(s) 13871)

The cor. of secs. 32 and 33 only, monumented with an alum. pipe, ½" dia., firmly set, protruding 10" above ground, from which the original bearing trees:

A down Hemlock 16" dia., bears N.7½°E., 38 lks. dist., with healed blaze.

A sawed Hemlock stump 28" dia., bears S.73½°W., 50 lks. dist. with healed blaze. (Rec. brg. S.75°W.)

A Fir 8" dia., bears N.68°W., 35 lks. dist., with scribe marks 23S R8W visible on opened blaze. (Rec. brg. N.65°W.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 23 S R 8 W

S 32 | S 33

S 4

T 24 S

1963

from which a new bearing tree:

A Hemlock 45" dia., bears N.82°E., 52 lks. dist., mkd. T23S R8W S33 BT.

Reset the aluminum pipe alongside the iron post.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Jan. 1967 - C.S. File 54/12-20

Found - 1963 Cadastral brass cap, properly mkd. with ½" pipe alongside.

Orig. 16" Hemlock now broken and high stumped, N.7½°E., 25.1 ft., blaze chopped open and scribe visible. (Cont. Next Page)

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 301700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33 T23-8 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Orig. 28" Hemlock stump S.73½°W. 33.0 ft., shows old scar.
Orig. 8" Hemlock, not Fir, N.68°W., 23.1 ft., dead and nearly pushed over, scribe visible on chopped out blaze.
45" Hemlock N.82°E., 34.3 ft., turned out and burned, scribe visible.
New BT - 40" Fir stump N.51°E., 17.1 ft. mkd. T23S R8W S33 CS BT.
Corner lies on West edge of cat road, nearly buried.

Tony Hostetter - For: Weyerhaeuser Co. - July 2003 - M142-67

Found - 1963 brass cap & accessories as described by Tracy in 1967 - C.S. 54/12
14" Fir, WEYCO tag & nail, bears S.16°W., 10.8 ft. to "W" nail.
16" Fir, WEYCO tag & nail, bears N.60°W., 13.3 ft. to "W" nail.

Stephan Stys - Crew: Brandon Campbell & John Rondeau - 11/27/2022 - C.S. File 65/111-35

Found - A 2½" iron rod w/ a ¾" brass cap w/no visible markings and a 1/2" aluminum pipe and a t-post along side. Set per DCS0 recs Vol. 33, Pg 13871.
A 14" D.Fir w/a tag but no visible markings bears S.16°W., 10.8' (Per map file M142-67).
A 20" D.Fir w/a tag but no visible markings bears N.60°W., 13.3' (Per map file M142-67). Added an X-chop.
New - A 22" D.Fir, faced & scribed "SW S33 BT" with X-chop and tag bears N.29°E., 8.0' to a spike at side center.
A 6" D.Fir, faced & scribed "X BT" with X-chop and tag bears S.23°W., 15.6' to a spike at side center.
Note - Lat. and long. per GARMIN ETREX HANDHELD GPS and does not produce survey grade coordinates.
N: 43°31'08.7" W: ~~123°31'51.0"~~ *
* should be 123°39'51.0" per DCS0 4/2026
Compass declination: 18° East