

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3340)

Set a post 3½ ft. long, 3" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S on W. face, from which
A Fir 30" dia., bears N.65°E., 56 lks. dist. mkd. ¼ S BT.
A Fir 20" dia., bears S.10°W., 29 lks. dist. mkd. ¼ S BT.

BLM corner remonumentation by Harold D. Corbin, Cadastral Surveyor, under Group #'s 350 and 427, Surveyed June 1959 - (DCSO records Vol. 30 Page(s) 12609)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 24 S R 8 W
 ¼
 S 33|S 34
 1959

from which

- A Hemlock 13" dia., bears N.88½°E., 30 lks. dist. mkd. ¼ S34 BT.
- A W.Fir 7" dia., bears S.49°W., 29 lks. dist. mkd. ¼ S33 BT.

David Edwards - For: Seneca Jones Tbr Co - 3/2005 - M 147-35

-
- Found - Brass cap
23" hemlock N.88½°E., 9.80' w/healed blaze.
 - 12" Fir snag S.49°W., 19.14' w/healed blaze
 - New - 9" hemlock S.81°W., 10.65' scribed S33 BT.
 - Set 6 foot steel post 6' north.