

PRIMARY CORNER DESCRIPTION Sec. Cor. for 21, 22, 27 and 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3343)

Set a post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 21, 22, 27 and 28 marked ,T24S S22 on NE.; R8W S27 on SE.; S28 on SW.; and S21 on NW. faces, with 2 notches on S. and 3 notches on E. edges, from which
A Fir 20" dia., bears N.41°E., 63 lks. dist. mkd. T24S R8W S22 BT.
A Fir 20" dia., bears S.52½°E., 33 lks. dist. mkd. T24S R8W S27 BT.
A Fir 30" dia, bears S.37°W., 109 lks. dist. mkd. T24S R8W S28 BT.
A Fir 20" dia., bears N.4°W., 73 lks. dist. mkd. T24S R8W S21 BT.

BLM corner remonumentation by Harold D. Corbin, Cadastral Surveyor, under Group #'s 350 and 427, Surveyed June 1959 - (DCSO records Vol. 30 Page(s) 12614-15)

The sec. cor., determined at record bearing and distance from the original bearing trees:
A sawed Fir stump 35" dia., bears N.41°E., 63 lks. dist., with a healed blaze.
A Fir 38" dia., bears S.52½°E., 33 lks. dist. with a healed blaze.
A rotted Fir stump 35" dia., bears S.37°W., 109 lks. dist. with illegible scribe marks visible on partially opened blaze.
A Fir 40" dia., N.4°W., 73 lks. dist. with a healed blaze.

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
T 24 S R 8 W
S 21 | S 22
S 28 | S 27
1959

from which
A W.Fir 7" dia., bears N.13°E., 36 lks. dist. mkd. T24S R8W S22 BT.
A W.Fir 7" dia., bears S.16°E., 52 lks. dist. mkd. T24S R8W S27 BT.
A Hemlock 13" dia., bears S.33½°W., 83 lks. dist. mkd. T24S R8W S28 BT.
A W.Fir 7" dia., bears N.18½°W., 41 lks. dist. mkd. T24S R8W S21 BT.

(Cont. Next Page)

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 400300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 21, 22, 27 and 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. and used in BLM resurvey by C. Albert White;, Cadastral Surveyor and Donald R. Beck, Surveying Technician - under Group #427, Surveyed July/Aug. 1962 - (DCS0 records Vol. 32 Page(s) 13321)

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 3/11/2019 (Filed 11/17/2021) - C.S. File 67/50-16

-
- Found - A 3¼" dia., brass cap on a 2" I.D. iron pipe flush with ground (properly marked)
- A 30" dia., 2 ft tall rotted fir stump with a healed blaze; bears N.41°E., 41.6 ft. (per record) OBT
 - A 39" dia., 50 ft. tall D.Fir snag with FHSB and Timber Co. "Z" in bark; bears S.52½°E., 20.8 ft. (rec. S.52½°E., 21.8 ft.) OBT
 - A 24" dia., D.Fir (not W.Fir) with FHSB bears N.13°E., 23.0 ft. (rec. 23.8 ft.) 1959 BLM
 - A 21" dia., G.Fir (aka W.Fir) with FHSB; bears S.16°E., 34.2 ft. (per record) 1959 BLM
 - A mostly rotted away tip out, root hole near rec. B&D (S.33½°W., 27.1 ft) 1959 BLM
 - A 19" dia., D.Fir (not a W.Fir) with FHSB; bears N.18½°W., 26.0 ft. (rec. 27.1 ft) 1959 BLM