

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3348)

 Set a post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 9, 10, 15 and 16, marked, T24S S10 on NE.; R8W S15 on SE.; S16 on SW.; and S9 on NW. faces, with 4 notches on S. and 3 notches on E. edges, from which
 A Fir 40" dia., bears N.83½°E., 24 lks. dist. mkd. T24S R8W S10 BT.
 A Fir 20" dia., bears S.43°E., 35 lks. dist. mkd. T24S R8W S15 BT.
 A Cedar 50" dia., bears S.62°W., 24 lks. dist. mkd. T24S R8W S16 BT.
 A Fir 30" dia., bears N.23°W., 8 lks. dist. mkd. T24S R8W S9 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew June 27, 1967 - C.S. File 54/55-6

 Found - Orig. 40" now 48" Fir N.83½°E., 15.8 ft., alive, we open and shows scribe marks.
 Orig. 20" now 39" Fir, S.43°E., 23.1 ft., alive, shows good scar. Do not open. Rescribe in bark "T24S R8W S15 CS BT"
 Orig. 50" Cedar now only remains of stump S.62°W., 15.8 ft., no scribe found.
 Orig. 30" now 41" Fir N.23°W., 5.3 ft., alive, shows good scar. Do not open.

Set Brass cap at cor. mkd: County Surveyors Office

T 24 S R 8 W
 S 9 | S 10
 S 16 | S 15
 1967

New BTs- 65" D.Fir N.68°E., 21.8 ft. mkd. T24S R8W S10 CS BT
 7" D.Fir S.2°W., 23.7 ft. mkd. T24S R8W S16 CS BT.
 6" Hemlock N.74°W., 29.3 ft. mkd. T24S R8W S9 CS BT
 This corner lies 30 ft. N. of spur, sloping NE. and 1 tally North of old jeep road on ridge top.